



VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 61/TP/2024

Date: 25/9/2024

REFERENCE

Date of loss: 9/9/2024
Claimant: Cheah Wei Siong

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBV7774P	Make &	Yamaha
Reg date:	4/12/2023	Model	XSR155 Manual
Colour:	Blue	Engine No:	G3S7E0040773
Type:	Motorbike	Chassis No:	MH3RG4760NK047589
Type of Claims:	Third Party	Odometer No:	23979km
		Engine Cap:	155cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition:	Good	Steering:	N.A.	Engine Modification:	Nil
Paint work:	Good	Front brake:	Good	Pre-accident	
		Footbrake:	Good	Damage:	Nil

CONDITION OF TYRES

Front Wheel Size: Pirelli 110/70-17 70%
Rear Wheel Size: Pirelli 140/70-17 70%
The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS

	Repairer S\$	Adjuster S\$
Parts	S 2,803.50	S 2,803.50
Labour	S 1,340.00	S 1,060.00
Calculated Cost (S\$) :	S 4,143.50	S 3,863.50


Recommended Lump Sum Repair Cost (S\$) : \$ 3,000.00

Date of Assignment: 21/9/2024
Date Inspected: 21/9/2024
Est. repair Period: 05 days

Inspected At: Ah Fook Motor. Com LLP
5 Soon Lee Street
#01-15 Pioneer Point
Singapore 627607

POINT OF IMPACT

Damaged at the right hand front portion.



BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle along Penjuru Road .

GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted is at the right hand front portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$4,143.50. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$3,000.00.

We have not authorised the repair. Under normal circumstances, estimated **05** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Dave Chang
Automotive Appraiser
AUTO. ENG, CAE, CGI
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Front handle bar	bent/necessary	\$ 255.00	\$ 255.00 ✓
2	1 set	Front fork assy	bent/necessary	\$ 1,455.00	\$ 1,455.00 (100)
3	1	Front fork stem	necessary	\$ 105.00	\$ 105.00 46
4	1	Front fork bearing	necessary	\$ 65.00	\$ 65.00 ✓
5	1 set	Front side cover	warped/grazed	\$ 95.00	\$ 95.00 ✓
6	1	Front brake disc	warped	\$ 215.00	\$ 215.00 195
7	1	Front fender repair	bent/necessary	\$ 275.00	\$ 275.00 XR
8	1	Front wheel rim	warped	\$ 650.00	\$ 650.00 365
				\$ 3,115.00	\$ 3,115.00
		Less 10%	2121 10%	\$ 311.50	\$ 311.50
			1908.90	\$ 2,803.50	\$ 2,803.50
		Total parts		\$ 2,803.50	\$ 2,803.50

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour to replace accident affected area.	\$ 500.00	\$ 400.00 300
2	To transport bike to workshop.	\$ 80.00	\$ 60.00 40
3	To putty and spray paint affected area.	\$ 500.00	\$ 400.00 200
4	To conduct chassis alignment.	\$ 140.00	\$ 120.00 X
5	To check wheel alignment.	\$ 60.00	\$ 40.00 ✓
6	To balance front wheel.	\$ 30.00	\$ 20.00 ✓
7	To check lighting and wiring.	\$ 30.00	\$ 20.00 10
Total labour :		\$ 1,340.00	\$ 1,060.00

610

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 2,803.50	\$ 2,803.50
Total labour :	\$ 1,340.00	\$ 1,060.00
Total repair cost :	\$ 4,143.50	\$ 3,863.50

Adjusted Repair Cost (Lump Sum Repair)

\$ 3,000.00

1908.90
 610.00
 2518.90
 20%
 2015.12
 45 - \$2,000 / 3 days