



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBV 7774P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT HANDLE BAR	BENT/NECESSARY	255.00	255.00
1	SET FRONT FORK ASSY	BENT/NECESSARY	1,455.00	1,100.00
1	FRONT FORK STEM	NECESSARY	105.00	46.00
1	FRONT FORK BEARING	NECESSARY	65.00	65.00
1	SET FRONT SIDE COVER	WARPED/GRAZED	95.00	95.00
1	FRONT BRAKE DISC	WARPED	215.00	195.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	275.00	-
1	FRONT WHEEL RIM	WARPED	650.00	365.00
	LESS 10% DISCOUNT		-311.50	-212.10
			2,803.50	1,908.90
	<b><u>LABOUR</u></b>			
	LABOUR TO REPLACE ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF FRONT FENDER.		500.00	300.00
	TO TRANSPORT BIKE TO WORKSHOP.		80.00	40.00
	TO PUTTY AND SPRAY PAINT AFFECTED AREA.		500.00	200.00
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	140.00	-
	TO CHECK WHEEL ALIGNMENT.		60.00	40.00
	TO BALANCE FRONT WHEEL.		30.00	20.00
	TO CHECK LIGHTING AND WIRING.		30.00	10.00
			1,340.00	610.00
<b>GRAND TOTAL</b>			<b>4,143.50</b>	<b>2,518.90</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,000.00</b>

Report Ref No. CS/LIP24090220/Rqh3m4(N)

MARKET VALUE: \$16,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,186.00=NETT VALUE: \$6,814.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.