



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24090223/Avh3
75 BRAS BASAH ROAD	Date:	02/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNR 894B	Veh. Inspected	SMS 5538D
Policy No.	-	Coverage	0
Claim No.	MT/1294426-002	Excess	\$0.00
Assign From	JULIE	Assign Date	13/09/2024

### 2. Vehicle Details

Make & Model	HONDA JAZZ	C.C	1318
Engine No.	L13B15000502	Year of Reg.	02/03/2020
Chassis No.	JHMGK3850LS217661	Colour	GREY
Odometer	299081 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/55 R15	YOKOHAMA	6
L/H Front Tyre	195/55 R15	YOKOHAMA	6
R/H Rear Tyre	195/55 R15	YOKOHAMA	6
L/H Rear Tyre	195/55 R15	YOKOHAMA	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	07/09/2024	Inspection Date	18/09/2024 (15:30)
Survey held at	CHIA AUTO SERVICES PTE LTD 23 KAKI BUKIT AVENUE 4 #02-03A AAS KAKI BUKIT CENTRE SINGAPORE 415933		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days