

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG124090226/TVP3E2**Date:** 15/10/2024REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** FBW610U**Insured Vehicle No :** YR603U

Date of Loss: 10/09/2024

Nature of Claim: TP

Claim No: CDMCG24002346

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBW610U**

Make &amp; Model: YAMAHA AEROX 155A, 155cc

Engine No: G3P4E0143617

Reg. Date: 14/02/2024 (Man. Year: 2023)

Chassis No: MH3SG6410PJ241491

Colour: Red

Odometer: 0 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80 R14 Rear Tyre Size: 140/70 R14

Front Left Side: IRC 5 mm Rear Left Side: IRC 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,023.00	475.20	547.80	53.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	590.00	440.00	150.00	25.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>1,613.00</b>	<b>915.20</b>	<b>697.80</b>	<b>43.26</b>

INSPECTION

Date of Assignment: 12/09/2024

Date Inspected: 16/09/2024

Inspected At:

Kim Hock Motor Pte Ltd (HQ)  
Blk 27A Jurong Port Road #01-19  
Singapore 619101

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 Oct 2024)	
Parts:	N/A	YAMAHA AEROX 155A 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBW610U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EXHAUST PIPE ASSY	Repair	495.00 F	*- FL
2	1		*EXHAUST PIPE COVER	Cut	85.00 F	*85.00 FL
3	1		*REAR MUDGUARD	Cut	98.00 F	*98.00 FL
4	1		*REAR BOX BRACKET	Bent	185.00 F	*185.00 FL
5	1		*REAR GRAB PIPE	Distorted	80.00 F	*80.00 FL
6	1		*BOX BRACKET	Bent	80.00 F	*80.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					1,023.00	528.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	52.80
Total Parts (\$\$)					1,023.00	475.20

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING	New	45.00	45.00
2	TOWING TO IDAC	New	45.00	45.00
3	LABOUR	New	500.00	350.00
<b>Gross Labour Cost (\$)</b>			<b>590.00</b>	<b>440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >