

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090231/RPA3Q2  
Date: 17/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006372\_03  
Claimant Vehicle No : PD544L Insured Vehicle No : SHD2296J  
Date of Loss: 21/08/2024 Nature of Claim: TP Claim No: MFL2024D0009846

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PD544L  
Make & Model: TOYOTA HIACE, 2.8 D COMMUTER GL (A) Engine No: 1GD8971098  
Reg. Date: 27/10/2022 (Man. Year: 2022) Chassis No: GDH2232004582  
Colour: White Odometer: 101842 km  
Engine Capacity: 2754 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15  
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm  
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,255.00	1,485.00	1,770.00	54.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	550.00	630.00	53.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,435.00</b>	<b>2,035.00</b>	<b>2,400.00</b>	<b>54.11</b>
<b>+ GST 9.00/9.00% (S\$)</b>	399.15	183.15	216.00	54.11
<b>Nett Amount (S\$)</b>	<b>4,834.15</b>	<b>2,218.15</b>	<b>2,616.00</b>	<b>54.11</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.18		
<b>Nett Liability (S\$)</b>		<b>2,520.33</b>		

INSPECTION

Date of Assignment: 18/09/2024  
Date Inspected: 18/09/2024 Inspected At: Mova Automotive Pte Ltd (Bukit Merah)  
Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3  
Singapore 159722  
Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2024)
Parts:	213	TOYOTA HIACE 2.8 D COMMUTER GL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PD544L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	1,300.00 FL	*1,300.00 FL
2	1		*HEADLAMP LH	Not Necessary	1,700.00 FL	*- FL
3	1		*FRONT SIDE PANEL LH (NPA)	Repair	0.00 FL	*- FL
4	1		*FRONT DOOR LH (NPA)	Repair	0.00 FL	*- FL
5	1		*FRONT STEP PANEL LH	Not Necessary	490.00 FL	*- FL
6	1		*FRONT TYRE CAP LH	Not Necessary	170.00 FL	*- FL
7	1		*SIDE MIRROR ASSY LH	Cracked	680.00 FL	*680.00 FL
					<b>Sub Total (\$\$)</b>	<b>4,340.00 1,980.00</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,085.00 495.00</b>
					<b>Total Parts (\$\$)</b>	<b>3,255.00 1,485.00</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CUT WELD ,PANEL BEAT ,STRAIGHTEN,REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS	New	500.00	300.00
2	TO PUTTY SPRAY PAINT ON FRONT DOOR LH ,FRONT SIDE PANEL LH	New	450.00	250.00
3	TO RESET & REPROGRAMMING AFTER ACCIDENT REPAIR WORKS	New	150.00	0.00
4	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,180.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >