

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24090232/KQP3E2
Date: 21/10/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001927694
Claimant Vehicle No :	SLP6675L	Insured Vehicle No :	SMJ1868A
Date of Loss:	11/09/2024	Nature of Claim:	TP
		Claim No:	373043

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP6675L	Engine No:	1ZRY348527
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L (A)	Chassis No:	MR053REH104563030
Reg. Date:	14/06/2017 (Man. Year: 2016)	Odometer:	106583 km
Colour:	Metallic Brown		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,107.87	12,302.79	7,805.08	38.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,890.00	1,710.00	47.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,707.87	14,192.79	9,515.08	40.13
Approved Total (Overridden) (S\$)		11,350.00		
(S\$)	23,707.87	11,350.00	12,357.87	52.13
+ GST 9.00/9.00% (S\$)	2,133.71	1,021.50	1,112.21	52.13
Nett Amount (S\$)	25,841.58	12,371.50	13,470.08	52.13

INSPECTION

Date of Assignment:	13/09/2024	
Date Inspected:	13/09/2024	Inspected At: Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2024)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP6675L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,743.90 FL	*1,418.40 FL
2	2		*FRONT BONNET HINGES LH & RH	Repair	163.60 FL	*- FL
3	1		*FRONT HEADLAMP LH	Cracked	4,617.90 FL	*3,243.20 FL
4	1		*FRONT HEADLAMP BRACKET LH (NPA)	Not Necessary	0.00 FL	*- FL
5	1		*FRONT BUMPER	Cracked	905.40 FL	*589.60 FL
6	1		*FRONT BUMPER SIDE RETAINER LH	Cracked	130.80 FL	*130.80 FL
7	1		*FRONT FOG LAMP LH	Mtg Cracked	473.20 FL	*315.00 FL
8	1		*FRONT FOGLAMP GARNISH LH	Serviceable	171.60 FL	*- FL
9	1		*AIR BOX ASSY	Cracked	1,582.40 FL	*195.00 FL
10	1		*FRONT FENDER LH	Bent	1,386.90 FL	*761.45 FL
11	1		*FRONT FENDER INNER SHIELD LH	Torn	381.30 FL	*226.60 FL
12	1		*FRONT SHOCK ABSORBER LH	Bent	676.30 FL	*676.30 FL
13	1		*FRONT SHOCK ABSORBER SPRING LH	Serviceable	230.00 FL	*- FL
14	1		*FRONT SHOCK ABSORBER MOUNTING LH	Serviceable	303.30 FL	*- FL
15	1		*FRONT SHOCK ABSORBER DUST COVER LH	Serviceable	46.50 FL	*- FL
16	1		*STEERING RACK	Bent/Jammed	2,732.00 FL	*2,732.00 FL
17	1		*FRONT DRIVE SHAFT LH	Bent	1,663.70 FL	*1,663.70 FL
18	1		*FRONT KNUCKLE ARM LH	Bent	878.60 FL	*585.00 FL
19	1		*FRONT WHEEL BEARING LH	Necessary	100.80 FL	*100.80 FL
20	1		*FRONT WHEEL BEARING HUB LH	Bent	362.50 FL	*362.50 FL
21	1		*FRONT ANTI ROLL BAR LH	Serviceable	582.20 FL	*- FL
22	1		*FRONT ANTI ROLL BAR LINKAGE LH	Serviceable	328.00 FL	*- FL
23	1		*FRONT LOWER ARM LH	Distorted	1,113.90 FL	*543.90 FL
24	1		*FRONT CROSSMEMBER	Serviceable	2,803.60 FL	*- FL
25	1		*RIM	Dented	3,032.10 FL	*2,512.80 FL
26	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
27	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*50.00 FS
28	1		*TYRE (80%)	Punctured	200.00 FS	*160.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,710.50	16,317.05
- List Item Discount on L Items 25.00/25.00% (\$\$)	6,602.63	4,014.26
Total Parts (\$\$)	20,107.87	12,302.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,500.00	1,000.00
2	LABOUR REMOVE / REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,500.00	550.00
3	TO CHECK WIRING SYSTEM	New	100.00	20.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	60.00
5	WHEEL ALIGNMENT	New	100.00	60.00
6	TO REMOVE / REPLACE / REFIX / CHECK UNDERCARRIAGE	New	280.00	200.00
Gross Labour Cost (\$\$)			3,600.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >