

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG24090233/RVP3M4**Date:** 12/12/2024REFERENCE

Insured/Claimant:	Lim Tau Liang Terence	Policy No:	1002966659	
Date of Loss:	11/09/2024	Nature of Claim:	OD	Claim No: 373082

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ1550E		
Make & Model:	MERCEDES-BENZ C200, 2.0 AVANTGARDE (R17 LED) (A)	Engine No:	27492030478461
Reg. Date:	04/01/2016 (Man. Year: 2015)	Chassis No:	WDD2050422R122169
Colour:	White	Odometer:	0 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	S\$48,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,457.97	8,386.79	3,071.18	26.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	23,140.00	17,420.00	5,720.00	24.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,597.97	25,806.79	8,791.18	25.41
+ GST 9.00/9.00% (S\$)	3,113.82	2,322.61	791.21	25.41
Nett Amount (S\$)	37,711.79	28,129.40	9,582.39	25.41

INSPECTION

Date of Assignment:	13/09/2024	
Date Inspected:	13/09/2024	Inspected At: CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378
Estimated Period of Repair:	18.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$3,071.18 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2024)
Parts:	143	MERCEDES-BENZ C200 2.0 AVANTGARDE (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ1550E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BATTERY SENSOR	Necessary	448.90 FS	*448.90 FS
2	1		*INSULATING CAP	Necessary	9.33 FS	*9.33 FS
3	1		*INSULATING CAP	Necessary	9.33 FS	*9.33 FS
4	1		*CURRENT LIMITER	Necessary	441.74 FS	*441.74 FS
5	1		*EQUIPMENT COMPARTMENT	Necessary	120.75 FS	*120.75 FS
6	1		*RH/FRONT RELAY UNIT	Necessary	591.71 FS	*591.71 FS
7	1		*FUSE CARRIER	Necessary	6.31 FS	*6.31 FS
8	1		*COVER EQP. COMPARTMENT	Necessary	49.13 FS	*49.13 FS
9	1		*INFO SHT. RELAYS + FUSES	Necessary	8.61 FS	*8.61 FS
10	1		*ENGINE ELECTRICAL WIRING HARNESS	* Check	2,611.73 FS	*- FS
11	1		*FUSE BOX ELECTRICAL WIRING HARNESS	Necessary	168.72 FS	*168.72 FS
12	1		*MAIN ELECTRICAL WIRING HARNESS	Necessary	5,749.95 FS	*5,749.95 FS
13	1		*RIGHT WHEEL HOUSE PARTITION	Necessary	137.87 FS	*137.87 FS
14	1		*CTR/FIREWALL PARTITION	Necessary	190.74 FS	*190.74 FS
15	1		*DAMPENING, FIREWALL	* Check	196.05 FS	*- FS
16	1		*RIGHT WATER BAFFLE	* Check	263.40 FS	*- FS
17	1		*RIGHT SIDE SEAL, AIR DUCT	Necessary	14.89 FS	*14.89 FS
18	1		*SEALING, AIR DUCT	Necessary	56.04 FS	*56.04 FS
19	2		*EXPANSION RIVET	Necessary	6.66 FS	*6.66 FS
20	1		*FEED-THROUGH GROMMET	Necessary	2.92 FS	*2.92 FS
21	1		*RIGHT DRAIN VALVE	Necessary	58.65 FS	*58.65 FS
22	1		*LEFT WATER BAFFLE	Necessary	314.54 FS	*314.54 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 11,457.97 8,386.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL AFFECTED BODY PANEL FOR REPAIRS	New	3,840.00	1,920.00
2	RESPRAY ENGINE HOOD	New	1,440.00	1,000.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT	New	380.00	380.00
4	EXTRACT REFRIGERANT, CHECK FOR LEAKS, REFILL WHEN WORKING ON AIR CONDITIONING)	New	500.00	500.00
5	FRAME FLOOR WIRING HARNESS REPLACE WITH REMOVE/INSTALL EVAPORATOR UNIT INSTRUMENT PANEL & HEADLINER & STEERING COLUMN & AIRBAG & FUSE BOX DETACHABLE PARTS IN AREA TO BE REPAIRED	New	14,400.00	12,480.00
6	TO WASH FIRE EXTINGUISHER POWDER	New	1,440.00	480.00
7	TO DROP AND REFIT / RENEW ABR PUMP AND CONTROL UNIT, TO BLEED AND RESET ESP SYSTEM	New	960.00	480.00
8	CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM	New	180.00	180.00
Gross Labour Cost (\$\$)			23,140.00	17,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >