



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090236/Kvp3e2
16 RAFFLES QUAY	Date:	20/09/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3855U	Veh. Inspected	SNH 4730S
Policy No.	-	Coverage	0
Claim No.	D24007961MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	13/09/2024

### 2. Vehicle Details

Make & Model	TOYOTA ESTIMA (A)	C.C	2362
Engine No.	2AZF361677	Year of Reg.	05/02/2010
Chassis No.	ACR500108333	Colour	METALLIC PEARL WHITE
Odometer	320175 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55R17	BRIDGESTONE	6
L/H Front Tyre	215/55R17	BRIDGESTONE	6
R/H Rear Tyre	215/55R17	YOKOHAMA	6
L/H Rear Tyre	215/55R17	YOKOHAMA	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	10/09/2024	Inspection Date	17/09/2024
Survey held at	BLK 5034 #01-341 ANG MO KIO INDUSTRIAL PARK 2 (S) 569541 - REPAIRER: LH EXPRESS MOTOR TRADING		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days