

WDC2533462F410677

TP Somp 2021
Xiao Chen.Pro Selection Pte Ltd
Block 1 Kaki Bukit Ave 6
#01-06 Autobay@Kaki Bukit
Singapore 417883

SNT5335E Mercedes Benz GLC250

No	Qty	Parts Description	Condition	Estimated Parts Price
1	1	Rear bumper assy <i>De band</i>		\$ 3,653.00 <i>1690</i>
2	2	Rear bumper bracket <i>LH Pund</i>		\$ 128.00 <i>64</i>
3	2	Rear bumper retainer <i>LH crushed</i>		\$ 126.00 <i>63</i>
4	1 set	Rear bumper reflector <i>crushed</i>		\$ 288.00 <i>125</i>
5	1	Rear bumper lower garnish <i>De band</i>		\$ 2,187.00 <i>710</i>
6	1	Rear bumper tow cover <i>Not nec</i>		\$ 108.00 <i>x</i>
7	1	Rear bumper lower chrome moulding <i>cut</i>		\$ 256.00 <i>412</i>
8	2	Rear bumper inner garnish <i>LH Pund</i>		\$ 291.00 <i>145</i>
9	1	Rear bumper reinforcement <i>Dented</i>		\$ 792.00
10	1	Rear bumper inner beam <i>Sponge crushed</i>		\$ 605.00 <i>125</i>
11	1	Rear tailgate outer garnish <i>Not nec</i>		\$ 1,183.00 <i>x</i>
12	1	Rear tailgate assy <i>Dented</i>		\$ 4,852.00 <i>2965</i>
13	1	Rear tailgate lock mechanism <i>Damaged</i>		\$ 455.00 <i>✓</i>
14	1	Rear tailgate lock catch <i>Not nec</i>		\$ 86.00 <i>x</i>
15	1	Rear tailgate centre logo <i>Not nec</i>		\$ 178.00 <i>✓</i>
16	1	Rear tailgate tool inner tray <i>Not nec</i>		\$ 365.00 <i>x</i>
17	1	Rear tailgate weatherstrip <i>Not nec</i>		\$ 188.00 <i>x</i>
18	1	Rear tailgate inner trim board <i>Not nec</i>		\$ 495.00 <i>x</i>
19	1	Rear tailgate inner handle		\$ 175.00 <i>x</i>
20	1 set	Rear tailgate inner auto tailgate switches <i>Not nec</i>		\$ 255.00 <i>x</i>
21	1 set	Rear no plate lamp <i>Not nec</i>		\$ 220.00 <i>x</i>
22	1	Rear tailgate left taillamp <i>Crushed</i>		\$ 830.00 <i>✓</i>
23	1	Rear tailgate right taillamp <i>Not nec</i>		\$ 830.00 <i>x</i>
24	1	Rear left taillamp <i>Crushed</i>		\$ 1,175.00 <i>✓</i>
25	1	Rear right taillamp <i>Not nec</i>		\$ 1,175.00 <i>x</i>
26	2	Rear exhaust chrome tailpipe end <i>Not nec</i>		\$ 450.00 <i>x</i>
27	1	Rear exhaust muffler assy <i>Not nec</i>		\$ 3,650.00 <i>x</i>
28	2	Rear exhaust muffler rubber mounting <i>Not nec</i>		\$ 108.00 <i>x</i>
29	1	Rear end lower panel <i>Repair</i>		\$ 2,256.00 <i>x</i>
30	1	Rear end lower panel top garnish <i>Not nec</i>		\$ 287.00 <i>x</i>
31	1	Rear right fender inner garnish <i>Not nec</i>		\$ 524.00 <i>x</i>
32	1	Rear left fender inner garnish <i>Not nec</i>		\$ 524.00 <i>x</i>
				\$ 29,697.00
		less 10%		\$ 2,969.70
				\$ 26,727.30
<u>Special Nett Items</u>				
1	12	Rear bumper clips <i>New</i>		\$ 50.00 <i>✓</i>
2	8	Rear tailgate inner trim board clips <i>✓</i>		\$ 40.00 <i>x</i>
3	8	Rear tailgate outer garnish clips <i>✓</i>		\$ 40.00 <i>x</i>
4	4	Rear end lower panel top garnish clips <i>✓</i>		\$ 30.00 <i>x</i>
5	1	Rear end lower panel sealant <i>Not nec</i>		\$ 120.00 <i>x</i>
6	8	Rear left fender inner garnish clips <i>Not nec</i>		\$ 40.00 <i>x</i>
7	8	Rear right fender inner garnish clips <i>Not nec</i>		\$ 40.00 <i>x</i>
8	1	Rear view camera <i>Not nec</i>		\$ 650.00 <i>x</i>
9	1	Rear windscreen glass sealant <i>Not nec</i>		\$ 120.00 <i>x</i>
10	4	Rear bumper reverse sensor <i>1 piece damaged</i>		\$ 1,200.00 <i>300</i>
11	1	Rear no plate with garnish <i>Not nec</i>		\$ 120.00 <i>x</i>
				\$ 2,450.00
Total parts				\$ 29,177.30

410

Pro Selection Pte Ltd
Block 1 Kaki Bukit Ave 6
#01-06 Autobay@Kaki Bukit
Singapore 417883

SNT5335E Mercedes Benz GLC250

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,500.00
2	To putty and spray painting rear portion.	\$ 1,500.00
3	To check rear lighting and wiring.	\$ 50.00
4	To remove and install rear tailgate lock mechanism.	\$ 80.00
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00
6	To apply anti rust proofing to rear affected area.	\$ 140.00
7	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00
8	To remove and install rear view camera.	\$ 80.00
9	To remove and install rear exhaust muffler assy.	\$ 120.00
10	To remove and install rear bumper reverse sensor.	\$ 80.00
11	Towing service.	\$ 120.00
Total labour :		\$ 3,960.00

500
600
30
60
40
30
120
50
X
50
X

1480

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total parts : \$ 29,177.30
Total labour : \$ 3,960.00
Total repair cost : \$ 33,137.30

total: 10646.10

2/s: 8.5K

06 Days

8.5K

8.5K