

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24060160/EMA3Q2**Date:** 11/10/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700006159
Claimant Vehicle No : SHB8639A **Insured Vehicle No :** SLN7796A
Date of Loss: 19/06/2024 Nature of Claim: TP Claim No: 7869304559SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB8639A**
Make & Model: KIA NIRO PLUS HYBRID, 1.6 (A) Engine No: G4LENS090286
Reg. Date: 29/08/2023 (Man. Year: 2023) Chassis No: KNAA381CVPT015033
Colour: Silver Odometer: 70794 km
Engine Capacity: 1580 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55Z R17 Rear Tyre Size: 215/55Z R17
Front Left Side: Goddard 5 mm Rear Left Side: Goddard 5 mm
Front Right Side: Goddard 5 mm Rear Right Side: Goddard 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,529.20	4,301.01	7,228.19	62.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,042.00	1,566.00	2,476.00	61.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,571.20	5,867.01	9,704.19	62.32
+ GST 9.00/9.00% (S\$)	1,401.41	528.03	873.38	62.32
Nett Amount (S\$)	16,972.61	6,395.04	10,577.57	62.32
+ Car Rental (4.0 x S\$98.00/day) (S\$)		392.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		6,789.22		
Global Sum Settlement (S\$)		6,780.00		

INSPECTION

Date of Assignment: 20/06/2024
Date Inspected: 20/06/2024 Inspected At: STRIDES PREMIER AUTOMOTIVE SERVICES
PTE LTD (HQ)
23 CHANGI SOUTH AVE 2
Singapore 486443
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY ,REAR FOG & R/REFL RH (DISC 10%)	Cut	204.70 F	*184.23 F
2	10		*CLIPS PIECE ,RR BUMPER (DISC 10%)	Necessary	48.00 F	*43.20 F
3	1		*SKID PLATE -RR BUMPER (DISC 10%)	Cut	120.75 F	*108.67 F
4	1		*COVER -RR BUMPER FOG LAMP RH (DISC 10%)	Cut	26.45 F	*23.80 F
5	1		*COVER -RR BUMPER LWR (DISC 10%)	Cut	637.10 F	*573.39 F
6	1		*COVER RR BUMPER UPR (DISC 10%)	Crushed	615.25 F	*553.73 F
7	1		*EMBLEM -KIA (DISC 10%)	Necessary	51.75 F	*46.58 F
8	1		*EMBLEM -HYBRID (DISC 10%)	Necessary	26.45 F	*23.80 F
9	1		*EMBLEM -NIRO PLUS (DISC 10%)	Necessary	42.55 F	*38.29 F
10	1		*PANEL ASSY -TAIL GATE (DISC 10%)	Necessary	1,619.20 F	*1,457.28 F
11	1		*CLIP -SIDE GARNISH MTG (DISC 10%) (7 PCS)	Necessary	8.05 F	*7.24 F
12	1		*GARNISH ASSY -QTR SIDE RH (DISC 10%)	Cut	165.60 F	*149.04 F
13	1		*BEAM -RR BUMPER (DISC 10%)	Broken	691.15 F	*622.03 F
14	1		*MOULDING ASSY -RR BUMPER SIDE ,RH (DISC 10%)	Cut	17.25 F	*15.53 F
15	1		*ULTRASONIC SENSOR -S.P.A.S (DISC 10%)	Missing	203.55 F	*183.20 F
16	1		*NUMBER PLATE FRAME (SN)	Cut	25.00 F	*25.00 F
17	1		*NUMBER PLATE ((SN)	Bent	35.00 F	*35.00 F
18	3		*SEALANT W/SCREEN (3 PCS) (SN)	Necessary	111.00 F	*111.00 F
19	1		*STICKER LOGO (TAILGATE) (SN)	Necessary	50.00 F	*50.00 F
20	1		*STICKER LOGO (RR FENDER) (SN)	Necessary	50.00 F	*50.00 F
21	1		*CAP -RR HOOK	Not Necessary	6.90 F	*- F
22	1		*MOULDING ASSY ,RR BUMPER SIDE RH	Not Necessary	17.25 F	*- F
23	1		*COVER, RR BUMPER SIDE UNER RH	Not Necessary	13.80 F	*- F
24	1		*LAMP ASSY -LICENSE PLATE LH	Not Necessary	36.80 F	*- F
25	1		*ANTENNA ASSY -SMARTKEY	Not Necessary	44.85 F	*- F
26	1		*ULTRASONIC SENSOR -S.P.A.S	Not Necessary	203.55 F	*- F
27	1		*STAY -RR BUMPER RH	Not Necessary	67.85 F	*- F
28	1		*STAY -RR BUMPER LH	Not Necessary	67.85 F	*- F
29	1		*BRACKET -RR BEAM LWR CTR	Not Necessary	13.80 F	*- F
30	1		*BRACKET- RR BEAM UPR MTG RH	Not Necessary	5.75 F	*- F
31	1		*BRACKET- RR BEAM UPR MTG LH	Not Necessary	5.75 F	*- F
32	1		*BEAM RR BUMPER	Not Necessary	691.15 F	*- F
33	1		*BRACKET ASSY RR BUMPER SIDE RH	Not Necessary	28.75 F	*- F
34	1		*LAMP ASSY REAR COMBINSIDE RH	Not Necessary	757.85 F	*- F
35	1		*LAMP ASSY ,REAR COMBOUTSIDE RH	Not Necessary	920.00 F	*- F
36	1		*GLASS TAIL GATE	Not Necessary	1,575.50 F	*- F
37	1		*HINGE ASSY TAIL GATE	Not Necessary	36.80 F	*- F
38	1		*GUARD ASSY ,REAR WHEEL RH	Not Necessary	293.25 F	*- F
39	1		*PANEL ASSY -QUARTER OUTER RH	Repair	1,388.05 F	*- F
40	1		*PANEL ASSY -BACK	Repair	604.90 F	*- F

F=Franchise part.

Total Parts (\$\$) **11,529.20** **4,301.01**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,352.00	400.00
2	SPRAY PAINT	New	1,794.00	880.00
3	TOWING CHARGE	New	56.00	56.00
4	TO WASH AND VACUUM	New	60.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	30.00
6	TO APPLY RUST PROOFING ON AFFECTED AREA	New	200.00	0.00
7	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	50.00
8	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
9	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
10	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (\$\$)			4,042.00	1,566.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >