

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG24090239/AQP3M4**Date:** 06/12/2024REFERENCE

Insured/Claimant:	ONG THIAM HOCK	Policy No:	7210013751	
Date of Loss:	12/09/2024	Nature of Claim:	OD	Claim No: 6505243445SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX9150K		
Make & Model:	AUDI A3, 999cc SEDAN 1.0 TFSI S TRONIC (LED) (A)	Engine No:	CHZC34819
Reg. Date:	04/02/2021 (Man. Year: 2019)	Chassis No:	WAUZZZ8V3LA032941
Colour:	Blue	Odometer:	49161 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,808.00	17,801.44	10,006.56	35.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,792.00	8,862.00	2,930.00	24.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,600.00	26,663.44	12,936.56	32.67
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	39,000.00	26,063.44	12,936.56	33.17
+ GST 9.00/9.00% (S\$)	3,510.00	2,345.71	1,164.29	33.17
Nett Amount (S\$)	42,510.00	28,409.15	14,100.85	33.17

INSPECTION

Date of Assignment:	13/09/2024	
Date Inspected:	16/09/2024	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,736.00 FS	*2,188.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	209.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - LH	Cracked	49.00 FS	*38.56 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Deformed	645.00 FS	*515.60 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LH	Deformed	357.00 FS	*285.60 FS
6	1		*FRONT BUMPER TRIM - LH	Deformed	204.00 FS	*163.20 FS
7	1		*FRONT BUMPER ADAPTOR - LH	Not Necessary	48.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	1,784.00 FS	*1,427.20 FS
9	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	235.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	236.00 FS	*188.40 FS
11	1		*FRONT REINFORCEMENT BEAM COVER	Not Necessary	153.00 FS	*- FS
12	1		*FRONT FOAM FILLER PIECE	Cracked	237.00 FS	*189.60 FS
13	1		*FRONT REINFORCEMENT BEAM	Not Necessary	1,055.00 FS	*- FS
14	1		*OUTSIDE TEMP SENSOR BRACKET	Not Necessary	30.00 FS	*- FS
15	1		*LED HEADLIGHT - LH	Cracked	6,647.00 FS	*5,317.60 FS
16	1		*LED HEADLIGHT POWER MODULE - LH	Not Necessary	904.00 FS	*- FS
17	1		*LED HEADLIGHT CONTROL UNIT - LH	Not Necessary	664.00 FS	*- FS
18	1		*LIFT CYLINDER - LH	Damaged	170.00 FS	*136.00 FS
19	1		*LIFT CYLINDER HOSE	Cut	86.00 FS	*68.56 FS
20	1		*FRONT FENDER - LH	Distorted	1,016.00 FS	*812.80 FS
21	1		*FRONT FENDER ATTACHMENT PARTS - LH	Not Necessary	85.00 FS	*- FS
22	1		*FRONT FENDER BRACKET - LH	Bent	45.00 FS	*35.28 FS
23	1		*FRONT FENDER BRACKET - LH	Bent	72.00 FS	*57.28 FS
24	5		*FRONT FENDER RIVET	Necessary	21.00 FS	*16.80 FS
25	1		*FRONT FENDER BRACE	Bent	122.00 FS	*97.20 FS
26	1		*FRONT WHEEL HOUSING LINER SEAL - LH	Not Necessary	43.00 FS	*- FS
27	1		*FRONT WHEEL HOUSING LINER - LH	Deformed	204.00 FS	*162.80 FS
28	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PART	Not Necessary	105.00 FS	*- FS
29	1		*BONNET	Dented	3,392.00 FS	*2,713.60 FS
30	1		*BONNET ATTACHMENT PARTS	Not Necessary	184.00 FS	*- FS
31	2		*BONNET HINGE - LH / RH	Not Necessary	150.00 FS	*- FS
32	1		*BONNET CATCH HOOK	Not Necessary	116.00 FS	*- FS
33	2		*BONNET STRIKER - LH / RH	Not Necessary	274.00 FS	*- FS
34	1		*BONNET EDGE PROTECTION	Not Necessary	35.00 FS	*- FS
35	2		*BONNET LOCK WITH MICROSWITCH	Not Necessary	491.00 FS	*- FS
36	1		*WASH WATER RESERVOIR	Deformed	238.00 FS	*190.00 FS
37	1		*WASH WATER RESERVOIR STRAINER	Not Necessary	26.00 FS	*- FS
38	1		*WASH WATER RESERVOIR END CAP	Not Necessary	26.00 FS	*- FS
39	1		*WINDSCREEN WASHER PUMP	Not Necessary	147.00 FS	*- FS
40	1		*HORN	Damaged	239.00 FS	*190.80 FS
41	1		*ALUMINIUM RIM - LH	Cut	1,464.00 FS	*1,171.20 FS
42	1		*ALUMINIUM RIM RUBBER VALVE - LH	Not Necessary	5.00 FS	*- FS
43	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
44	1		*SUNDRIES	Necessary	600.00 FS	*17.36 FS
45	1		*FRONT LOCK CARRIER (Supplementary)	Cracked	908.00 FS	*726.00 FS
46	6		*MIX COOLANT 1.0 LITER (Supplementary)	Necessary	332.00 FS	*265.44 FS
47	1		*HEADLIGHT LED HEAT SINK LHS (Supplementary)	Cracked	924.00 FS	*738.80 FS
48	1		*AIRCON STICKER (Supplementary)	Necessary	10.00 FS	*7.52 FS
49	1		*CAUTION STICKER (Supplementary)	Necessary	25.00 FS	*19.44 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **27,808.00** **17,801.44**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, AND OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR	New	280.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,500.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR AND LHS A-PILLAR	New	4,000.00	2,750.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT	New	560.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
8	TO RE-APPLY PAINT PROTECTION FILM ON ACCIDENT AFFECTED PANELS (NPA)	New	0.00	0.00
9	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS (Supplementary)	New	1,400.00	1,400.00
10	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION (Supplementary)	New	1,250.00	1,250.00
11	TO REPAIR LHS FRONT FENDER TOP SUPPORT (Supplementary)	New	250.00	250.00
12	TO RESPRAY LHS FRONT FENDER TOP SUPPORT (Supplementary)	New	250.00	250.00
Gross Labour Cost (\$\$)			11,792.00	8,862.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >