



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090240/Rvp3m4
16 RAFFLES QUAY	Date:	21/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8958S	Veh. Inspected	SMZ 5629M
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24007997MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	13/09/2024

2. Vehicle Details

Make & Model	HONDA ODYSSEY 2.4 EX-S CVT	C.C	2356
Engine No.	K24W72540157	Year of Reg.	03/05/2021
Chassis No.	JHMRC1880MC200727	Colour	GREY
Odometer	44926 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60R17	YOKOHAMA	6
L/H Front Tyre	215/60R17	YOKOHAMA	6
R/H Rear Tyre	215/60R17	YOKOHAMA	6
L/H Rear Tyre	215/60R17	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/09/2024	Inspection Date	14/10/2024
Survey held at	KAH MOTOR CO SDN BERHAD - 255 ALEXANDRA ROAD, SINGAPORE 159937		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days