12/10/24, 9:58 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24090241/KMA3Q2

Date: 10/12/2024

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100485523 **Claimant Vehicle** SNP1219E

Insured Vehicle No: SLG7203G No:

Date of Loss: 12/09/2024 Nature of Claim: TP Claim No: 1631537286SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNP1219E**

Make & Model: TOYOTA SIENTA, 1.5 HYBRID (A) Engine No: M15AY446574

Reg. Date: 28/10/2022 (Man. Year: 2022) Chassis No: JTDBBBA350L000159

Colour: Metallic Pearl White Odometer: 62223 km

1490 cc **Engine Capacity:** Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Yes Engine Modification: No Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15 Front Left Side: Rear Left Side: Toyo 9 mm Falken 8 mm Front Right Side: Falken 8 mm Rear Right Side: Toyo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,881.10	1,831.10	50.00	2.66
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,150.00	530.00	620.00	53.91
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,031.10	2,361.10	670.00	22.10
	Approved Total (Overridden) (S\$)		1,850.00		
	(S\$)	3,031.10	1,850.00	1,181.10	38.97
	+ GST 9.00/9.00% (S\$)	272.80	166.50	106.30	38.97
	Nett Amount (S\$)	3,303.90	2,016.50	1,287.40	38.97
	+ Loss of Use (2.0 x S	660.00/day) (S\$)	120.00		
	+ Doc/S	Search Fee (S\$)	33.18		
	Ne	ett Liability (S\$)	2,169.68		
	Global Sum	Settlement (S\$)	2,150.00		

INSPECTION

Date of Assignment: 13/09/2024

Optima Werkz Pte Ltd (HQ)

10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Date Inspected: 13/09/2024 Inspected At:

Autopoint

Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: Daphne Lee Mooi Ngiuk NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR PANEL	Bent	1,991.90 FL	*1,991.90 FL
2	1		*FRONT LH DOOR OUTER LOWER MOULDING	Mtg Cracked	293.50 FL	*293.50 FL
3	1		*FRONT LH DOOR NO.1 BLACK OUT TAPE	Necessary	89.40 FL	*89.40 FL
4	1		*FRONT LH OUTER DOOR HANDLE (NPA)	Repair	0.00 FL	*- FL
5	1		*FRONT LH SIDE MIRROR (NPA)	Repair	0.00 FL	*-FL
6	1		*FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*-FS
7	1		*FRONT DOOR OUTER MOULDING CLIPS	Necessary	50.00 FS	*50.00 FS
F=Fra	inchise	part. S=SpcN	lett. L=ListItemDisc.	Sub Total (S\$)	2,474.80	2,424.80
			- List Item Discount on L Iter	ms 25.00/25.00% (S\$)	593.70	593.70
				Total Parts (S\$)	1,881.10	1,831.10
			Report was unsubmitted during this	print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	LABOUR CHARGES TO REMOVE REPLACE REFIX REPAIR & READJUST FRONT LH ACCIDENT AREAS & ETC	New	300.00	200.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT LH DOOR PANEL ,FRONT LH OUTER DOOR HANDLE ,FRONT LH SIDE MIRROR ETC	New	550.00	220.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC BACK TO ORIGINAL OPERATION	New	100.00	60.00
4	TO TUFF KOTE & UNDERSEAL MATERIALS	New	100.00	30.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM	New	100.00	20.00
	Gross Labo	our Cost (S\$)	1,150.00	530.00
	Report was unsubmitted during thi	is print-out.		

< END OF ESTIMATES >