

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090244/UPA3Q2**Date:** 28/11/2024REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070165575
Claimant Vehicle No : SJQ1790M **Insured Vehicle No :** SMW4741T
 Date of Loss: 15/09/2024 Nature of Claim: TP Claim No: 9361565499SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJQ1790M**
 Make & Model: HYUNDAI AVANTE, 1.6 HD DOHC ABS AIRBAG 2WD (A) Engine No: G4FC9U647377
 Reg. Date: 28/04/2009 (Man. Year: 2009) Chassis No: KMHDU41BR9U749932
 Colour: Grey Odometer: 163849 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
 Front Left Side: Tourador 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Tourador 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,726.40	7,641.36	9,085.04	54.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,280.00	3,630.00	1,650.00	31.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,006.40	11,271.36	10,735.04	48.78
Approved Total (Overridden) (S\$)		9,000.00		
(S\$)	22,006.40	9,000.00	13,006.40	59.10
+ GST 9.00/9.00% (S\$)	1,980.58	810.00	1,170.58	59.10
Nett Amount (S\$)	23,986.98	9,810.00	14,176.98	59.10
+ Car Rental (11.0 x S\$100.00/day + 9.00% GST) (S\$)		1,199.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		11,011.18		

INSPECTION

Date of Assignment: 16/09/2024
 Date Inspected: 16/09/2024 Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines)
 Blk 9006 #01-200 Tampines St 93
 Singapore
 Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	2,065.00 FL	*- FL
2	1		*BONNET LOCK	Not Necessary	80.00 FL	*- FL
3	1		*FRONT BUMPER	Dented Deformed	698.00 FL	*498.40 FL
4	2		*FRONT BUMPER SIDE REAINER	Not Necessary	120.00 FL	*- FL
5	2		*FRONT BUMPER BRACKET	Not Necessary	120.00 FL	*- FL
6	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	95.00 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Torn	159.00 FL	*145.80 FL
8	1		*FRONT BUMPER REINFORCEMENT	Dented	390.00 FL	*366.50 FL
9	2		*FOG LAMP GARNISH	Not Necessary	130.00 FL	*- FL
10	2		*HEADLAMP	Cracked	1,380.00 FL	*1,362.00 FL
11	2		*HEADLAMP LOWER BRACKET	Not Necessary	120.00 FL	*- FL
12	1		*FRONT SUPPORT PANEL	Cracked	992.00 FL	*942.80 FL
13	2		*RADIATOR AIR GUIDE	Not Necessary	80.00 FL	*- FL
14	1		*AIR CON CONDENSER	Not Necessary	1,298.00 FL	*- FL
15	1		*RADIATOR	Not Necessary	894.00 FL	*- FL
16	1		*RADIATOR FAN ASSY	Not Necessary	996.00 FL	*- FL
17	1		*BOOT LID	Dented / Bent	1,598.00 FL	*1,221.00 FL
18	1		*BOOT LID LOGO	Necessary	54.00 FL	*32.00 FL
19	1		*BOOT LID EMBLEM -AVANTE	Necessary	62.00 FL	*35.00 FL
20	1		*BOOT LID INSULATOR	Not Necessary	198.00 FL	*- FL
21	1		*BOOT LID LAMP	N/S Cracked / O/S Not Necessary	788.00 FL	*208.50 FL
22	2		*TAILLAMP	Cracked	996.00 FL	*690.00 FL
23	1		*REAR BUMPER	Distorted	792.00 FL	*486.90 FL
24	2		*REAR BUMPER SIDE RETAINER	Not Necessary	118.00 FL	*- FL
25	5		*REAR BUMPER BRACKET	Bent / Twisted	225.00 FL	*225.00 FL
26	1		*REAR BUMPER REINFORCEMENT	Cracked	498.00 FL	*354.00 FL
27	1		*REAR BUMPER REINFORCEMENT BRACKET	N/S Bent / O/S Not Necessary	396.00 FL	*95.00 FL
28	1		*REAR END PANEL	Dented	798.00 FL	*580.60 FL
29	1		*REAR END PANEL GARNISH	Twisted	68.00 FL	*68.00 FL
30	1		*SPARE TYRE PANEL	Crumpled / Buckled	1,198.00 FL	*1,085.20 FL
31	1		*SPARE TYRE PANEL BOARD	Warped	298.00 FL	*298.00 FL
32	1		*REAR FENDER INNER TRIM	N/S Torn / O/S Not Necessary	794.00 FL	*282.00 FL
33	1		*SPARE TYRE SPONGE	Not Necessary	198.00 FL	*- FL
34	1		*SPARE TYRE FASTENER	Not Necessary	112.00 FL	*- FL
35	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
36	1		*SET FRONT BUMPER RIVET	Not Necessary	50.00 FS	*- FS
37	1		*COOLANT	Not Necessary	40.00 FS	*- FS
38	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
39	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
40	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*40.00 FS
41	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
42	1		*SET REAR BUMPER RIVET	Not Necessary	50.00 FS	*- FS
43	2		*REAR BUMPER PROTECTOR	Necessary	500.00 FS	*80.00 FS
44	1		*SET REAR END PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS
45	1		*SPARE TYRE PANEL RUBBER INSULATOR	Necessary	450.00 FS	*80.00 FS
46	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
47	1		*SET REVERSE SENSOR	Malfunction	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 20,488.00 9,436.70
- List Item Discount on L Items 20.00/20.00% (\$\$) 3,761.60 1,795.34

Total Parts (\$\$) 16,726.40 7,641.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER BOOTLID MECHANISM	New	100.00	50.00
2	RESPRAY ANTI RUST	New	150.00	80.00
3	APPLY BODY SEALANT TO CAR JOINTS	New	150.00	0.00
4	TO VACCUM REOIL AND REGAS	New	150.00	0.00
5	TO CHECK LIGHT AND WIRING	New	50.00	30.00
6	INSTALL REVERSE SENSOR	New	100.00	30.00
7	TO REMOVE INNER TRIM GARNISH AND ETC TO FACILITATE REPAIRS AND TO FIX BACK	New	180.00	60.00
8	PANEL BEATING FOR REAR PORTION	New	1,200.00	1,100.00
9	PANEL BEATING FOR FRONT PORTION	New	800.00	580.00
10	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	New	2,400.00	1,700.00
Gross Labour Cost (\$\$)			5,280.00	3,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >