

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090245/AMA3Q2
Date: 17/03/2025

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D23MFL0002582_01
Claimant Vehicle No :	SMV8875U	Insured Vehicle No :	SLF3068L
Date of Loss:	13/09/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0010859

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV8875U		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2340868A
Reg. Date:	29/12/2016 (Man. Year: 2016)	Chassis No:	SJNFEAJ11U1797962
Colour:	Grey	Odometer:	160808 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,027.31	6,126.21	3,901.10	38.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	1,660.00	930.00	35.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,617.31	7,786.21	4,831.10	38.29
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	12,617.31	6,100.00	6,517.31	51.65
+ GST 9.00/9.00% (S\$)	1,135.56	549.00	586.56	51.65
Nett Amount (S\$)	13,752.87	6,649.00	7,103.87	51.65
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		7,376.25		
Global Sum Settlement (S\$)		7,350.00		

INSPECTION

Date of Assignment:	16/09/2024	
Date Inspected:	16/09/2024 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2024)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV8875U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	860.40 FL	*755.00 FL
2	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	133.80 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	746.20 FL	*619.00 FL
4	2		*REAR BUMPER REINFORCEMENT BRACKET L/R	Dented	304.80 FL	*304.80 FL
5	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	85.60 FL	*- FL
6	1		*REAR BUMPER SPONGE	Cracked	152.90 FL	*152.90 FL
7	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	30.00 FL	*- FL
8	1		*REAR END PANEL	Dented	573.40 FL	*573.40 FL
9	1		*REAR END PANEL INNER TOP GARNISH	Deformed	74.90 FL	*74.90 FL
10	1		*REAR EXHAUST SILENCER BOX (LOCAL REPAIR)	Dented	1,217.34 FS	*150.00 FS
11	1		*REAR TAILGATE	Dented	3,306.00 FL	*2,955.00 FL
12	1		*REAR TAILGATE LOGO EMBLEM	Not Necessary	70.00 FL	*- FL
13	1		*REAR TAILGATE QASHQAI EMBLEM	Not Necessary	101.90 FL	*- FL
14	2		*REAR TAILGATE DAMPER L/R	Not Necessary	594.00 FL	*- FL
15	2		*REAR TAILGATE HINGES L/R	Not Necessary	60.00 FL	*- FL
16	1		*REAR TAILGATE INNER PULL HANDLE	Not Necessary	25.00 FL	*- FL
17	2		*REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	Not Necessary	30.00 FL	*- FL
18	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	125.00 FL	*- FL
19	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	37.50 FL	*- FL
20	1		*REAR TAILGATE MECHANISM LOCK	Damaged	205.50 FL	*205.50 FL
21	1		*REAR TAILGATE WEATHERSTRIP	Cut	198.40 FL	*198.40 FL
22	1		*REAR TAILGATE WINDSCREEN WITH MOULDING	Necessary	1,068.00 FL	*168.00 FL
23	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
24	1		*SET REAR BUMPER REVERSE SENSOR (4 EYE)	Damaged	380.00 FS	*280.00 FS
25	1		*REAR BUMPER TOP CHROME MOULDING	Bent	180.00 FS	*150.00 FS
26	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
27	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
29	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
30	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
31	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,905.64	6,726.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	878.33	600.69
Total Parts (\$\$)	10,027.31	6,126.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH TRIM LINER CARPET (TO FR)	New	80.00	60.00
4	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
5	TO REMOVE AND CHARGE EXHAUST SILENCER BOX WITH PIPE ,REALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	100.00	80.00
6	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
7	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	60.00
8	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	60.00
Gross Labour Cost (\$\$)			2,590.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >