

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24090247/AQP3M4**Date:** 06/08/2025REFERENCE

Insured/Claimant: OGAWA HEALTH CARE PTE LTD Policy No: MCV24A00008400
Date of Loss: 10/09/2024 Nature of Claim: OD Claim No: DMCV2400183H/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ3136X**
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR MT (M) Engine No: 1KD2846046
Reg. Date: 15/03/2019 (Man. Year: 2019) Chassis No: JTFHT02P000248325
Colour: White Odometer: 190767 km
Engine Capacity: 2982 cc
Market Value/New Car Price: S\$58,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15C Rear Tyre Size: 195R15C
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,425.20	5,027.30	11,397.90	69.39
Miscellaneous Items	150.00	0.00	150.00	100.00
Labour	2,200.00	1,190.00	1,010.00	45.91
Paintwork Labour	1,100.00	900.00	200.00	18.18
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,875.20	7,117.30	12,757.90	64.19
Approved Total (Overridden) (S\$)		5,700.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	19,275.20	5,100.00	14,175.20	73.54
+ GST 9.00/9.00% (S\$)	1,734.77	459.00	1,275.77	73.54
Nett Amount (S\$)	21,009.97	5,559.00	15,450.97	73.54

INSPECTION

Date of Assignment: 16/09/2024 Present Location: Kan Fook Sing Motor Workshop (Defu)
KAN FOOK SING MOTOR WORKSHOP
Date Inspected: 16/09/2024 Inspected At: BLK.8 JTC DEFU INDUSTRIAL CITY
#04-29 DEFU SOUTH STREET 1
SINGAPORE 533758
Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 Aug 2025)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO 5DR MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ3136X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WIPER GARNISH (WCP)	Cut	320.00 F	*320.00 F
2	1		*FRONT BONNET (WCP)	Dented	380.00 F	*380.00 F
3	1		*FRONT BONNET LOCK (WCP)	Not Necessary	85.00 F	*- F
4	1		*FRONT BONNET HINGE RH (WCP)	Bent	48.00 F	*48.00 F
5	1		*FRONT BONNET HINGE LH (WCP)	Not Necessary	48.00 F	*- F
6	1		*FRONT HEADLAMP RH (WCP)	Smashed	550.00 F	*550.00 F
7	1		*FRONT HEADLAMP LH (WCP)	Not Necessary	550.00 F	*- F
8	1		*FRONT GRILLE TOP (WCP)	Not Necessary	115.00 F	*- F
9	1		*FRONT GRILLE LOWER (WCP)	Not Necessary	155.00 F	*- F
10	1		*FRONT GRILLE BASE (WCP)	Not Necessary	265.00 F	*- F
11	8		*FRONT GRILLE CLIP	Necessary	40.00 F	*20.00 FS
12	1		*FRONT BUMPER (WCP)	Distorted	300.00 F	*300.00 F
13	1		*FRONT BUMPER REINFORCEMENT (WCP)	Dented	250.00 F	*250.00 F
14	1		*FRONTBUMPER FOGLAMP COVER RH (WCP)	Deformed	25.00 F	*25.00 F
15	1		*FRONT BUMPER TOP BEAM (WCP)	Not Necessary	145.00 F	*- F
16	1		*FRONT BUMPER SIDE RETAINER RH (WCP)	Damaged	85.00 F	*85.00 F
17	1		*FRONT BUMPER SIDE FUSES COVER RH (WCP)	Smashed	85.00 F	*85.00 F
18	1		*FRONT CORNER PANEL RH (WCP)	Dented	135.00 F	*135.00 F
19	1		*FRONT DOOR RH (WCP)	Buckled	800.00 F	*800.00 F
20	1		*FRONT DOOR HINGE TOP RH (WCP)	Not Necessary	65.00 F	*- F
21	1		*FRONT DOOR HINGE LOWER RH (WCP)	Not Necessary	65.00 F	*- F
22	1		*FRONT DOOR CHECKER RH (WCP)	Not Necessary	85.00 F	*- F
23	1		*FRONT DOOR TRIMBOARD RH (WCP)	Not Necessary	580.00 F	*- F
24	1		*FRONT DOOR RUBBER RH (WCP)	Not Necessary	125.00 F	*- F
25	1		*FRONT DOOR LOCK RH (WCP)	Not Necessary	285.00 F	*- F
26	1		*FRONT WINDSCREEN PILLAR RH (WCP)	Repair	585.00 F	*- F
27	1		*FRONT STEP GARNISH RH (WCP)	Not Necessary	120.00 F	*- F
28	1		*FIRE WALL PANEL (WCP)	Repair	1,000.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	1		*BRAKE BOOSTER ASSY (WCP)	Damaged	950.00 F	*950.00 F
30	1		*BRAKE MASTER PUMP (WCP)	Damaged	580.00 F	*580.00 F
31	1		*BRAKE PIPE (WCP)	Not Necessary	65.00 F	*- F
32	3		*BRAKE PIPE (NPA)	Not Necessary	-	*- F
33	1		*INTERCOOLER (WCP)	Not Necessary	660.00 F	*- F
34	1		*INTERCOOLER GARNISH RH (WCP)	Not Necessary	85.00 F	*- F
35	1		*INTERCOOLER GARNISH LH (WCP)	Not Necessary	105.00 F	*- F
36	1		*AIR CON CONDENSER (WCP)	Not Necessary	620.00 F	*- F
37	1		*RADIATOR (WCP)	Not Necessary	750.00 F	*- F
38	1		*WIRE HARNESS (WCP)	Not Necessary	2,000.00 F	*- F
39	1		*DASHBOARD (WCP)	Not Necessary	700.00 F	*- F
40	1		*HEADLAMP CLIP RH	Necessary	18.00 F	*10.00 FS
41	1		*HEADLAMP CLIP LH (WCP)	Not Necessary	18.00 F	*- F
42	1		*FRONT BUMPER VERTICAL BRACKET RH (WCP)	Not Necessary	65.00 F	*- F
43	1		*FRONT BUMPER VERTICAL BRACKET LH (WCP)	Not Necessary	65.00 F	*- F
44	1		*FRONT BUMPER TOW COVER (WCP)	Not Necessary	15.00 F	*- F
45	10		*FRONT BUMPER CLIP (WCP)	Necessary	35.00 F	*35.00 F
46	1		*FRONT SUPPORT PANEL (WCP)	Repair	280.00 F	*- F
47	1		*FRONT SUPPORT LOWER BRACKET RH (WCP)	Not Necessary	115.00 F	*- F
48	1		*FRONT BRACE PANEL (WCP)	Not Necessary	65.00 F	*- F
<u>Supplementary #1</u>						
49	1		*AIR CLEANER ASSY (WCP)	Not Necessary	450.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	14,932.00	4,573.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,493.20	454.30
Total Parts (\$\$)	16,425.20	5,027.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	2	BRAKE FLUID (Not Necessary)	50.00	0.00
2	1	FRONT NUMBER PLATE (Not Necessary)	50.00	0.00
3	1	FRONT WINDSCREEN GUM (Not Necessary)	50.00	0.00
Sub Total (\$\$)			150.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAYPAINTING CHARGES	New	1,100.00	900.00
Labour Items				
2	TO CHECK WIRING SYSTEM	New	150.00	30.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	120.00	100.00
4	TO REMOVE/REFIT BRAKE SYSTEM	New	150.00	100.00
5	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	80.00	60.00
6	TO REMOVE/REFIT DASHBOARD TO FACILITATE FIRE WALL PANEL REPAIR	New	250.00	0.00
7	TO REMOVE/REFIT ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	1,450.00	900.00
Gross Labour Cost (\$\$)			3,300.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >