

REF:

ASSIGNMENT

Front: _____ Date: _____
 Estin: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To in Vehicle No: _____
 at W/O _____
 of _____
 Insured: _____
 Policy No: _____
 Claim's No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

Remark: There had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBJ 3B6X Yr Regn: 2019, March.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.O. 2982
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 190767 T/Radio: Insured / Std / NI / NA

Eng/No: JTFHT02P000248325
 C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C
 R: 195 R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

R/Bal. 06 mmL/Bal. 06 mm

D.O.A.

Rear

R/Bal. _____ mm

L/Bal. _____ mm

D.O.I. 16/09/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

DD Feels

COE Expiry :

Estimate given during : Yes C ✓
 1st Survey : No C ✓

MV: 58KPV: 11KNett: 47K

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)

Survey Fee:

Transportation:

S + R.S. \$1

Photos

Others

Report Form:

Report Form:



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MCV24A00008400	Date of Loss:	10/09/2024
Vehicle Reg. No.:	GBJ3136X	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	OGAWA HEALTH CARE PTE LTD		
Make/Model:	TOYOTA HIACE, 3.0 D TURBO (M)	Vehicle Reg. Date:	15/03/2019
Vehicle Colour:	METALLIC SILVER	Chassis No:	JTFHT02P000248325
Engine No:	1KD2846046		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS

	Amount
Parts	15,930.20
Miscellaneous Items	150.00
Labour	2,200.00
Paintwork Labour	1,100.00
Towing	0.00
Calculated Gross Total (S\$)	19,380.20
- Excess (S\$)	600.00
(S\$)	18,780.20
+ GST 9.00% (S\$)	1,690.22
Nett Amount (S\$)	20,470.42

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Sep 2024)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Kan Fook Sing Motor Workshop/GBJ3136X/10/09/2024 17:23	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WIPER GARNISH <i>lit</i>	0.00	0.00	✓ *320.00 F
2	1		*FRONT BONNET <i>Dented</i>	0.00	0.00	✓ *380.00 F
3	1		*FRONT BONNET LOCK <i>new</i>	0.00	0.00	+ *85.00 F
4	1		*FRONT BONNET HINGE RH <i>But</i>	0.00	0.00	✓ *48.00 F
5	1		*FRONT BONNET HINGE LH <i>new</i>	0.00	0.00	+ *48.00 F
6	1		*FRONT HEADLAMP RH <i>sanded</i>	0.00	0.00	✓ *550.00 F
7	1		*FRONT HEADLAMP LH <i>new</i>	0.00	0.00	+ *550.00 F
8	1		*FRONT GRILLE TOP <i>?</i>	0.00	0.00	? *115.00 F
9	1		*FRONT GRILLE LOWER <i>?</i>	0.00	0.00	? *155.00 F
10	1		*FRONT GRILLE BASE <i>?</i>	0.00	0.00	? *265.00 F
11	8		*FRONT GRILLE CLIP <i>new</i>	0.00	0.00	20 *40.00 F
12	1		*FRONT BUMPER <i>Dented</i>	0.00	0.00	✓ *300.00 F
13	1		*FRONT BUMPER REINFORCEMENT <i>Dented</i>	0.00	0.00	✓ *250.00 F
14	1		*FRONT BUMPER FOG LAMP COVER RH <i>Dented</i>	0.00	0.00	✓ *25.00 F
15	1		*FRONT BUMPER TOP BEAM <i>?</i>	0.00	0.00	? *145.00 F
16	1		*FRONT BUMPER SIDE RETAINER RH <i>Dented</i>	0.00	0.00	✓ *85.00 F
17	1		*FRONT BUMPER SIDE FUSES COVER RH <i>sanded</i>	0.00	0.00	✓ *85.00 F
18	1		*FRONT CORNER PANEL RH <i>Dented</i>	0.00	0.00	✓ *135.00 F
19	1		*FRONT DOOR RH <i>Budd</i>	0.00	0.00	✓ *800.00 F
20	1		*FRONT DOOR HINGE TOP RH <i>?</i>	0.00	0.00	? *65.00 F
21	1		*FRONT DOOR HINGE LOWER RH <i>?</i>	0.00	0.00	? *65.00 F
22	1		*FRONT DOOR CHECKER RH <i>?</i>	0.00	0.00	? *85.00 F
23	1		*FRONT DOOR TRIMBOARD RH <i>?</i>	0.00	0.00	? *580.00 F
24	1		*FRONT DOOR RUBBER RH <i>new</i>	0.00	0.00	+ *125.00 F
25	1		*FRONT DOOR LOCK RH <i>new</i>	0.00	0.00	? *285.00 F
26	1		*FRONT WINDSCREEN PILLAR RH <i>Ry</i>	0.00	0.00	+ *585.00 F
27	1		*FRONT STEP GARNISH RH <i>new</i>	0.00	0.00	+ *120.00 F
28	1		*FIRE WALL PANEL <i>Ry</i>	0.00	0.00	+ *1,000.00 F
29	1		*BRAKE BOOSTER ASSY <i>?</i>	0.00	0.00	? *950.00 F
30	1		*BRAKE MASTER PUMP <i>?</i>	0.00	0.00	? *580.00 F
31	1		*BRAKE PIPE <i>?</i>	0.00	0.00	? *65.00 F
32	3		*BRAKE PIPE <i>?</i>	0.00	0.00	-
33	1		*INTERCOOLER <i>?</i>	0.00	0.00	+ *660.00 F
34	1		*INTERCOOLER GARNISH RH <i>new</i>	0.00	0.00	+ *85.00 F
35	1		*INTERCOOLER GARNISH LH <i>new</i>	0.00	0.00	+ *105.00 F
36	1		*AIR CON CONDENSER <i>new</i>	0.00	0.00	+ *620.00 F
37	1		*RADIATOR <i>new</i>	0.00	0.00	+ *750.00 F
38	1		*WIRE HARNESS <i>new</i>	0.00	0.00	+ *2,000.00 F
39	1		*DASHBOARD <i>new</i>	0.00	0.00	+ *700.00 F
40	1		*HEADLAMP CLIP RH <i>new</i>	0.00	0.00	10 *18.00 F
41	1		*HEADLAMP CLIP LH <i>new</i>	0.00	0.00	+ *18.00 F
42	1		*FRONT BUMPER VERTICAL BRACKET RH <i>?</i>	0.00	0.00	? *65.00 F
43	1		*FRONT BUMPER VERTICAL BRACKET LH <i>new</i>	0.00	0.00	+ *65.00 F
44	1		*FRONT BUMPER TOW COVER <i>new</i>	0.00	0.00	+ *15.00 F
45	10		*FRONT BUMPER CLIP <i>new</i>	0.00	0.00	✓ *35.00 F

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*FRONT SUPPORT PANEL <i>Repis</i>	0.00	0.00	+ *280.00 F
47	1		*FRONT SUPPORT LOWER BRACKET RH ?	0.00	0.00	> *115.00 F
48	1		*FRONT BRACE PANEL <i>not new</i>	0.00	0.00	+ *65.00 F

F=Franchise part.

Sub Total (\$\$)

14,482.00

+ Margin on L,N Items 10.00% (\$\$)

1,448.20

Total Parts (\$\$)

15,930.20

Kan Fook Sing Motor Workshop/GBJ3136X/10/09/2024 17:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	2	BRAKE FLUID <i>new</i>	✓	50.00
2	1	FRONT NUMBER PLATE <i>not new</i>	✗	50.00
3	1	FRONT WINDSCREEN GUM <i>not new</i>	✗	50.00

Sub Total (\$\$) 150.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 SPRAYPAINTING CHARGES

New

900 1,100.00

Labour Items

2 TO CHECK WIRING SYSTEM

New

30 150.00

3 TO REMOVE/REFIT/REFILL AIR CON GAS

New

? 120.00

4 TO REMOVE/REFIT BRAKE SYSTEM

New

100 150.00

5 TO TRANSFER DOOR MECHANISM TO NEW DOOR

New

60 80.00

6 TO REMOVE/REFIT DASHBOARD TO FACILITATE FIRE WALL PANEL REPAIR

New

+ 250.00

7 TO REMOVE/REFIT ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS

New

900 1,450.00

Gross Labour Cost (\$\$) 3,300.00

Kan Fook Sing Motor Workshop/GBJ3136X/10/09/2024 17:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li
P/p 16/09/24
08 Days