

REF:

CA/1C924090247/Aq3

ASSIGNMENT

Front: _____ Date: _____

Estin: _____

OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MV

To In _____ Vehicle No: _____

at W _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBJ3B6X Yr Regn: 2019, March.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.D. 2982Colour: White A/C: Insured / Std / NI / NASp. Reading: 190767 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFHT02P000248325Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195R15CR: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. _____ mmL/Bal. 06 mm L/Bal. _____ mmD.O.A. _____ D.O.I. 16/09/24Survey held at Kan Fook Shing

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof top or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

DD FeesCOE ExpiryEstimate given during : Yes (✓)
1st Survey : No ()MV : 58KPV : 11KNett : 47K

Date/Time, File Pass to?



: Preli. Report

1)

Date/Time, File Return to?



: Final Report

2)

Report Form ref: _____

Main Form / L.P. / C.

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Inve (\$)

Survey Fee:

Transportation:

S + RS. \$1

Photos

Others



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MCV24A00008400	Date of Loss:	10/09/2024
Vehicle Reg. No.:	GBJ3136X	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	OGAWA HEALTH CARE PTE LTD		
Make/Model:	TOYOTA HIACE, 3.0 D TURBO (M)	Vehicle Reg. Date:	15/03/2019
Vehicle Colour:	METALLIC SILVER		
Engine No:	1KD2846046	Chassis No:	JTFHT02P000248325
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS

	Amount
Parts	15,930.20
Miscellaneous Items	150.00
Labour	2,200.00
Paintwork Labour	1,100.00
Towing	0.00
Calculated Gross Total (S\$)	19,380.20
- Excess (S\$)	600.00
(S\$)	18,780.20
+ GST 9.00% (S\$)	1,690.22
Nett Amount (S\$)	20,470.42

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Sep 2024)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Kan Fook Sing Motor Workshop/GBJ3136X/10/09/2024 17:23	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WIPER GARNISH <i>lit</i>	0.00	0.00	✓ *320.00 F
2	1		*FRONT BONNET <i>Detel</i>	0.00	0.00	✓ *380.00 F
3	1		*FRONT BONNET LOCK <i>new</i>	0.00	0.00	+ *85.00 F
4	1		*FRONT BONNET HINGE RH <i>Best</i>	0.00	0.00	✓ *48.00 F
5	1		*FRONT BONNET HINGE LH <i>new</i>	0.00	0.00	+ *48.00 F
6	1		*FRONT HEADLAMP RH <i>smoked</i>	0.00	0.00	✓ *550.00 F
7	1		*FRONT HEADLAMP LH <i>new</i>	0.00	0.00	+ *550.00 F
8	1		*FRONT GRILLE TOP ?	0.00	0.00	? *115.00 F
9	1		*FRONT GRILLE LOWER ?	0.00	0.00	? *155.00 F
10	1		*FRONT GRILLE BASE ?	0.00	0.00	? *265.00 F
11	8		*FRONT GRILLE CLIP <i>new</i>	0.00	0.00	20- *40.00 F
12	1		*FRONT BUMPER <i>Detel</i>	0.00	0.00	✓ *300.00 F
13	1		*FRONT BUMPER REINFORCEMENT <i>Detel</i>	0.00	0.00	✓ *250.00 F
14	1		*FRONT BUMPER FOGLAMP COVER RH <i>Detel</i>	0.00	0.00	✓ *25.00 F
15	1		*FRONT BUMPER TOP BEAM ?	0.00	0.00	? *145.00 F
16	1		*FRONT BUMPER SIDE RETAINER RH <i>Detel</i>	0.00	0.00	✓ *85.00 F
17	1		*FRONT BUMPER SIDE FUSES COVER RH <i>smoked</i>	0.00	0.00	✓ *85.00 F
18	1		*FRONT CORNER PANEL RH <i>Detel</i>	0.00	0.00	✓ *135.00 F
19	1		*FRONT DOOR RH <i>Detel</i>	0.00	0.00	✓ *800.00 F
20	1		*FRONT DOOR HINGE TOP RH ?	0.00	0.00	? *65.00 F
21	1		*FRONT DOOR HINGE LOWER RH ?	0.00	0.00	? *65.00 F
22	1		*FRONT DOOR CHECKER RH ?	0.00	0.00	? *85.00 F
23	1		*FRONT DOOR TRIMBOARD RH ?	0.00	0.00	? *580.00 F
24	1		*FRONT DOOR RUBBER RH <i>new</i>	0.00	0.00	+ *125.00 F
25	1		*FRONT DOOR LOCK RH <i>new</i>	0.00	0.00	? *285.00 F
26	1		*FRONT WINDSCREEN PILLAR RH <i>R/R</i>	0.00	0.00	+ *585.00 F
27	1		*FRONT STEP GARNISH RH <i>new</i>	0.00	0.00	+ *120.00 F
28	1		*FIRE WALL PANEL <i>R/R</i>	0.00	0.00	+ *1,000.00 F
29	1		*BRAKE BOOSTER ASSY ?	0.00	0.00	? *950.00 F
30	1		*BRAKE MASTER PUMP ?	0.00	0.00	? *580.00 F
31	1		*BRAKE PIPE ?	0.00	0.00	? *65.00 F
32	3		*BRAKE PIPE ?	0.00	0.00	? -
33	1		*INTERCOOLER ?	0.00	0.00	+ *660.00 F
34	1		*INTERCOOLER GARNISH RH <i>NP</i>	0.00	0.00	+ *85.00 F
35	1		*INTERCOOLER GARNISH LH <i>new</i>	0.00	0.00	+ *105.00 F
36	1		*AIR CON CONDENSER	0.00	0.00	+ *620.00 F
37	1		*RADIATOR <i>new</i>	0.00	0.00	+ *750.00 F
38	1		*WIRE HARNESS <i>new</i>	0.00	0.00	+ *2,000.00 F
39	1		*DASHBOARD <i>new</i>	0.00	0.00	+ *700.00 F
40	1		*HEADLAMP CLIP RH <i>new</i>	0.00	0.00	10- *18.00 F
41	1		*HEADLAMP CLIP LH <i>new</i>	0.00	0.00	+ *18.00 F
42	1		*FRONT BUMPER VERTICAL BRACKET RH ?	0.00	0.00	? *65.00 F
43	1		*FRONT BUMPER VERTICAL BRACKET LH <i>new</i>	0.00	0.00	+ *65.00 F
44	1		*FRONT BUMPER TOW COVER <i>new</i>	0.00	0.00	+ *15.00 F
45	10		*FRONT BUMPER CLIP <i>new</i>	0.00	0.00	✓ *35.00 F

Kan Fook Sing Motor Workshop/GBJ3136X/10/09/2024 17:23. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*FRONT SUPPORT PANEL <i>Rep 5</i>	0.00	0.00	+ *280.00 F
47	1		*FRONT SUPPORT LOWER BRACKET RH ?	0.00	0.00	> *115.00 F
48	1		*FRONT BRACE PANEL <i>not new</i>	0.00	0.00	+ *65.00 F

F=Franchise part.

Sub Total (S\$)	14,482.00
+ Margin on L,N Items 10.00% (S\$)	1,448.20
Total Parts (S\$)	15,930.20

Kan Fook Sing Motor Workshop/GBJ3136X/10/09/2024 17:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	2	BRAKE FLUID <i>new</i>	✓ 50.00
2	1	FRONT NUMBER PLATE <i>new</i>	50.00
3	1	FRONT WINDSCREEN GUM <i>new</i>	50.00
Sub Total (S\$)			150.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	SPRAYPAINTING CHARGES	New	<i>900</i> 1,100.00
Labour Items			
2	TO CHECK WIRING SYSTEM	New	<i>30</i> 150.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	<i>?</i> 120.00
4	TO REMOVE/REFIT BRAKE SYSTEM	New	<i>100</i> 150.00
5	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	<i>60</i> 80.00
6	TO REMOVE/REFIT DASHBOARD TO FACILITATE FIRE WALL PANEL REPAIR	New	<i>+</i> 250.00
7	TO REMOVE/REFIT ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	<i>900</i> 1,450.00
Gross Labour Cost (S\$)			3,300.00

Kan Fook Sing Motor Workshop/GBJ3136X/10/09/2024 17:23. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin L's
P/p 16/09/24
08 Days