

ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE038987
VEHICLE NO. : GBJ3136X
ACCIDENT DATE : 10-09-2024 08:00
THIRD PARTY REF. : SNK8976H

INVOICE NO : TEST
DATE : 05-10-2024

ATTN: ECICS LIMITED
INVOICE COST OF REPAIRS TO VEHICLE GBJ3136X TOYOTA HIACE

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT WIPER GARNISH	320.00
1	FRONT BONNET	380.00
2	FRONT BONNET HINGES @\$48.00	48.00
2	HEAD-LAMP @\$550.00	550.00
1	FRONT GRILLE (TOP)	115.00
1	FRONT GRILLE (LOWER)	155.00
1	FORNT GRILLE BASE	265.00
1	FRONT BUMPER	300.00
1	FRONT BUMPER REINFORCEMENT	250.00
1	FRONT BUMPER FOG LAMP COVER (RH)	25.00
1	FRONT BUMPER SIDE RETAINER (RH)	85.00
1	FRONT BUMPER SIDE FUSE COVER RH	85.00
1	SIDE CORNER (RH)	135.00
1	FRONT DOOR (RH)	800.00
1	BRAKE BOOSTER ASSY	950.00
1	BRAKE MASTER PUMP	580.00
10	FRONT BUMPER CLIP@\$3.50	35.00
1	AIR CLEANER ASSY	450.00 *
		5528.00
ADD 10 %		552.80
TOTAL (A)		6080.80

SPECIAL NETT ITEMS

2 BRAKE FLUID @\$25.00 50.00

VEHICLE NO. : GBJ3136X
ACCIDENT DATE : 10-09-2024 08:00
THIRD PARTY REF. : SNK8976H

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	FRONT GRILLE CLIP @\$5.00	20.00
1	HEADLAMP CLIP@\$18.00	10.00
TOTAL (C)		80.00

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	30.00
1	REMOVE & REFILL AIR CON GAS	120.00
1	REMOVE & REFIX BRAKE SYSTEM	100.00
1	REMOVE & REFIX DOOR COMPONENT PARTS,ETC	60.00
1	REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS,WELD/CUT, PANEL B-EATING & RENEW PARTS	900.00
1	SPRAY PAINTING CHARGES	900.00
TOTAL (D)		2,110.00
TOTAL REPAIR COST :		8270.80
G S T % :		690.37
EXCESS AMOUNT :		600.00
INVOICE AMOUNT :		8361.17

lamp Sum
\$ 6600

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 10 Sep 2024)

Parts: N/A TOYOTA HIACE 3.0 D TURBO (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/GBJ3136X/10/09/2024 17:23

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WIPER GARNISH <i>lit</i>	0.00	0.00	✓ *320.00 F
2	1		*FRONT BONNET <i>Detel</i>	0.00	0.00	✓ *380.00 F
3	1		*FRONT BONNET LOCK <i>new</i>	0.00	0.00	✗ *85.00 F
4	1		*FRONT BONNET HINGE RH <i>Detel</i>	0.00	0.00	✓ *48.00 F
5	1		*FRONT BONNET HINGE LH <i>new</i>	0.00	0.00	✗ *48.00 F
6	1		*FRONT HEADLAMP RH <i>smoked</i>	0.00	0.00	✓ *550.00 F
7	1		*FRONT HEADLAMP LH <i>new</i>	0.00	0.00	✗ *550.00 F
8	1		*FRONT GRILLE TOP ?	0.00	0.00	? *115.00 F
9	1		*FRONT GRILLE LOWER ?	0.00	0.00	? *155.00 F
10	1		*FRONT GRILLE BASE ?	0.00	0.00	? *265.00 F
11	8		*FRONT GRILLE CLIP <i>new</i>	0.00	0.00	20 *40.00 F
12	1		*FRONT BUMPER <i>Detel</i>	0.00	0.00	✓ *300.00 F
13	1		*FRONT BUMPER REINFORCEMENT <i>Detel</i>	0.00	0.00	✓ *250.00 F
14	1		*FRONT BUMPER FOG LAMP COVER RH <i>Detel</i>	0.00	0.00	✓ *25.00 F
15	1		*FRONT BUMPER TOP BEAM ?	0.00	0.00	? *145.00 F
16	1		*FRONT BUMPER SIDE RETAINER RH <i>Detel</i>	0.00	0.00	✓ *85.00 F
17	1		*FRONT BUMPER SIDE FUSES COVER RH <i>smoked</i>	0.00	0.00	✓ *85.00 F
18	1		*FRONT CORNER PANEL RH <i>Detel</i>	0.00	0.00	✓ *135.00 F
19	1		*FRONT DOOR RH <i>Detel</i>	0.00	0.00	✓ *800.00 F
20	1		*FRONT DOOR HINGE TOP RH ?	0.00	0.00	? *65.00 F
21	1		*FRONT DOOR HINGE LOWER RH ?	0.00	0.00	? *65.00 F
22	1		*FRONT DOOR CHECKER RH ?	0.00	0.00	? *85.00 F
23	1		*FRONT DOOR TRIMBOARD RH ?	0.00	0.00	? *580.00 F
24	1		*FRONT DOOR RUBBER RH <i>new</i>	0.00	0.00	✗ *125.00 F
25	1		*FRONT DOOR LOCK RH <i>new</i>	0.00	0.00	? *285.00 F
26	1		*FRONT WINDSCREEN PILLAR RH <i>Ry</i>	0.00	0.00	✗ *585.00 F
27	1		*FRONT STEP GARNISH RH <i>new</i>	0.00	0.00	✗ *120.00 F
28	1		*FIRE WALL PANEL <i>Ry</i>	0.00	0.00	✗ *1,000.00 F
29	1		*BRAKE BOOSTER ASSY ?	0.00	0.00	? *950.00 F
30	1		*BRAKE MASTER PUMP ?	0.00	0.00	? *580.00 F
31	1		*BRAKE PIPE ?	0.00	0.00	? *65.00 F
32	3		*BRAKE PIPE ?	0.00	0.00	? -
33	1		*INTERCOOLER	0.00	0.00	✗ *660.00 F
34	1		*INTERCOOLER GARNISH RH <i>new</i>	0.00	0.00	✗ *85.00 F
35	1		*INTERCOOLER GARNISH LH <i>new</i>	0.00	0.00	✗ *105.00 F
36	1		*AIR CON CONDENSER	0.00	0.00	✗ *620.00 F
37	1		*RADIATOR <i>new</i>	0.00	0.00	✗ *750.00 F
38	1		*WIRE HARNESS <i>new</i>	0.00	0.00	✗ *2,000.00 F
39	1		*DASHBOARD <i>new</i>	0.00	0.00	✗ *700.00 F
40	1		*HEADLAMP CLIP RH <i>new</i>	0.00	0.00	10 *18.00 F
41	1		*HEADLAMP CLIP LH <i>new</i>	0.00	0.00	✗ *18.00 F
42	1		*FRONT BUMPER VERTICAL BRACKET RH ?	0.00	0.00	? *65.00 F
43	1		*FRONT BUMPER VERTICAL BRACKET LH <i>new</i>	0.00	0.00	✗ *65.00 F
44	1		*FRONT BUMPER TOW COVER <i>new</i>	0.00	0.00	✗ *15.00 F
45	10		*FRONT BUMPER CLIP <i>new</i>	0.00	0.00	✓ *35.00 F

Kan Fook Sing Motor Workshop/GBJ3136X/10/09/2024 17:23. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*FRONT SUPPORT PANEL <i>Repis</i>	0.00	0.00	*280.00 F
47	1		*FRONT SUPPORT LOWER BRACKET RH ?	0.00	0.00	*115.00 F
48	1		*FRONT BRACE PANEL <i>not new</i>	0.00	0.00	*65.00 F

F=Franchise part.

Sub Total (S\$)	14,482.00
+ Margin on L,N Items 10.00% (S\$)	1,448.20
Total Parts (S\$)	15,930.20

Kan Fook Sing Motor Workshop/GBJ3136X/10/09/2024 17:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	2	BRAKE FLUID <i>nee</i>	50.00 ✓
2	1	FRONT NUMBER PLATE <i>nee nee</i>	50.00 <i>+</i>
3	1	FRONT WINDSCREEN GUM <i>nee nee</i>	50.00 <i>+</i>
Sub Total (S\$)			150.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	<i>900</i> 1,100.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	<i>30</i> 150.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	<i>?</i> 120.00
3	TO REMOVE/REFIT BRAKE SYSTEM	New	<i>100</i> 150.00
5	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	<i>60</i> 80.00
6	TO REMOVE/REFIT DASHBOARD TO FACILITATE FIRE WALL PANEL REPAIR	New	<i>+</i> 250.00
7	TO REMOVE/REFIT ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	<i>900</i> 1,450.00
Gross Labour Cost (S\$)			3,300.00

Kan Fook Sing Motor Workshop/GBJ3136X/10/09/2024 17:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adnan Li
P/p 16/09/24
08 Days.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Dec 2024)

Parts: N/A TOYOTA HIACE 3.0 D TURBO (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/GBJ3136X/16/12/2024 15:24

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR CLEANER ASSY	0.00	0.00	*450.00 F
						Sub Total (S\$) 450.00
						+ Margin on L,N Items 10.00% (S\$) 45.00
						Total Parts (S\$) 495.00

Kan Fook Sing Motor Workshop/GBJ3136X/16/12/2024 15:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Kan Fook Sing Motor Workshop/GBJ3136X/16/12/2024 15:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

