

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24090248/TUA3Q2  
**Date:** 11/02/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002582\_01  
**Claimant Vehicle No :** SNH3996Z **Insured Vehicle No :** SLQ8159S  
 Date of Loss: 14/09/2024 Nature of Claim: TP Claim No: MFL2024D0010736

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNH3996Z**  
 Make & Model: HYUNDAI CN7 AVANTE 1.6, 1.6 DOHC CVT S/R (A) Engine No: G4FMNU178274  
 Reg. Date: 26/10/2022 (Man. Year: 2022) Chassis No: KMHLN41ETNU322568  
 Colour: Grey Odometer: 35887 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17  
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm  
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,278.40	2,176.80	4,101.60	65.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,510.00	2,110.00	3,400.00	61.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,788.40</b>	<b>4,286.80</b>	<b>7,501.60</b>	<b>63.64</b>
<b>+ GST 9.00/9.00% (S\$)</b>	1,060.96	385.81	675.15	63.64
<b>Nett Amount (S\$)</b>	<b>12,849.36</b>	<b>4,672.61</b>	<b>8,176.75</b>	<b>63.64</b>
<b>+ Loss of Use (4.0 x S\$80.00/day) (S\$)</b>		320.00		
<b>+ Doc/Search Fee (S\$)</b>		2.18		
<b>Nett Liability (S\$)</b>		<b>4,994.79</b>		

**INSPECTION**

Date of Assignment: 17/09/2024  
 Date Inspected: 17/09/2024 Inspected At: Komoco Motors Pte Ltd (HQ)  
 253 ALEXANDRA ROAD, #01-01  
 Singapore 159936  
 Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** NA MENG YAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2024)
<b>Parts:</b> 143	HYUNDAI CN7 AVANTE 1.6 1.6 DOHC CVT S/R (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SNH3996Z)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*BUMPER CLIP	Necessary	20.00 FL	*20.00 FL
2	1		*COVER -FR BUMPER	Repair	605.00 FL	*- FL
3	1		*LIP -FRONT BUMPER	Not Necessary	53.00 FL	*- FL
4	1		*PANEL ASSY -FENDER LH	Bent	1,418.00 FL	*1,418.00 FL
5	1		*INSULATOR-FENDER LH	Not Necessary	45.00 FL	*- FL
6	1		*PANEL ASSY -FNDR APRON LH	Not Necessary	757.00 FL	*- FL
7	1		*GUARD ASSY-FRONT WHEEL LH	Necessary	95.00 FL	*95.00 FL
8	1		*WHEEL ASSY ,ALUMINIUM (17)	Cut	942.00 FL	*942.00 FL
9	1		*VALVE -TPMS	Necessary	221.00 FL	*221.00 FL
10	1		*LAMP ASSY -HEAD LH	Not Necessary	3,642.00 FL	*- FL
11	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,838.00</b>	<b>2,716.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,559.60	539.20
<b>Total Parts (\$\$)</b>	<b>6,278.40</b>	<b>2,176.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CARRY OUT ACCIDENT BODY REPAIR -FRT BUMPER /LH SIDE FENDER/LH FENDER APRON	New	2,400.00	960.00
2	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS -FRT BUMPER /LIP BUMPER /LH SIDE FENDER /LH FENDER APRON	New	1,800.00	720.00
3	TO R&I SIDE PANEL LH TO FACILITATE REPAIR	New	840.00	0.00
4	TO REALIGN HEADLAMP AFTER ACIDENT REPAIR	New	40.00	0.00
5	TO RENEW FRT LH WHEEL RIM	New	100.00	100.00
6	TO PERFORM 4 WHEEL ALIGNMENT	New	150.00	150.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR	New	180.00	180.00
			<b>Gross Labour Cost (S\$)</b>	<b>2,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >