

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

Our File No: CS/AIG24090249/TQP3M4  
Date: 24/01/2025

REFERENCE

Insured/Claimant: MATHILDA DE BOER-LIM WEN-SZE Policy No: 7240171637  
Date of Loss: 12/09/2024 Nature of Claim: OD Claim No: 1241627856SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLZ727H  
Make & Model: AUDI Q4, SPORTBACK 45 E-TRON (A) Engine No: HIDDEN  
Reg. Date: 29/08/2024 (Man. Year: 2024) Chassis No: WAUZZZFZ9RP074249  
Colour: Blue Odometer: 414 km  
Engine Capacity: 0 cc  
Market Value/New Car Price: S\$250,000.00  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R19 Rear Tyre Size: 235/55R19  
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm  
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,853.00	18,548.64	14,304.36	43.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,252.00	9,552.00	5,700.00	37.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,105.00	28,100.64	20,004.36	41.58
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	47,505.00	27,500.64	20,004.36	42.11
+ GST 9.00/9.00% (S\$)	4,275.45	2,475.06	1,800.39	42.11
Nett Amount (S\$)	51,780.45	29,975.70	21,804.75	42.11

INSPECTION

Date of Assignment: 16/09/2024  
Date Inspected: 17/09/2024 Inspected At: 24 BENOI SECTOR, SINGAPORE 629857  
Estimated Period of Repair: 8.0 days REPAIRER: PREMIUM AUTOMOBILES PTE LTD

Adjuster: MOHD TAUFIKH BIN HAMID Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,411.00 FS	*1,128.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	517.00 FS	*- FS
3	2		*FRONT BUMPER COVER CAP - LH / RH	Not Necessary	50.00 FS	*- FS
4	1		*FRONT BUMPER TRIM	Deformed	496.00 FS	*396.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Cracked	277.00 FS	*221.60 FS
6	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	236.00 FS	*- FS
7	1		*FRONT BUMPER GRILLE - CENTER1	Deformed	247.00 FS	*197.60 FS
8	1		*FRONT BUMPER SPOILER	Deformed	818.00 FS	*654.00 FS
9	1		*FROMT BUMPER IMPACT PROTECTION - SELENITE SIL	Distorted	545.00 FS	*436.00 FS
10	1		*FRONT BUMPER AIR DUCT	Deformed	109.00 FS	*86.80 FS
11	1		*RADIATOR GRILLE	Cracked	1,712.00 FS	*1,369.60 FS
12	1		*AUDI EMBLEM	Cut	202.00 FS	*161.60 FS
13	1		*VEHICLE ENVIRONMENT CAMERA	Not Necessary	1,298.00 FS	*- FS
14	1		*VEHICLE ENVIRONMENT CAMERA BRACKET	Not Necessary	53.00 FS	*- FS
15	1		*VEHICLE ENVIRONMENT CAMERA BRACKET SECURING	Not Necessary	42.00 FS	*- FS
16	2		*FRONT PARKING AID SENSOR	Not Necessary	600.00 FS	*- FS
17	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	57.00 FS	*- FS
18	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	122.00 FS	*- FS
19	1		*FRONT REINFORCEMENT BEAM	Bent	1,307.00 FS	*1,045.60 FS
20	1		*FRONT BUMPER SUPPORT	Not Necessary	57.00 FS	*- FS
21	1		*FRONT FOAM FILLER PIECE	Deformed	137.00 FS	*109.60 FS
22	2		*LED HEADLIGHT - LH / RH	Cracked	9,788.00 FS	*7,830.40 FS
23	2		*LED HEADLIGHT MOUNTING - LH / RH	Cracked	300.00 FS	*240.00 FS
24	2		*LIFT CYLINDER - LH / RH	Not Necessary	504.00 FS	*- FS
25	1		*LIFT CYLINDER HOSE - LH / RH	Not Necessary	128.00 FS	*- FS
26	1		*BONNET	Not Necessary	3,668.00 FS	*- FS
27	1		*BONNET ATTACHMENT PARTS	Not Necessary	133.00 FS	*- FS
28	2		*BONNET HINGE - LH / RH	Not Necessary	178.00 FS	*- FS
29	2		*BONNET STRIKER - LH / RH	Not Necessary	260.00 FS	*- FS
30	1		*BONNET IMPACT PROTECTION	Not Necessary	36.00 FS	*- FS
31	2		*BONNET LOCK - LH / RH	Not Necessary	982.00 FS	*- FS
32	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	71.00 FS	*- FS
33	1		*BONNET BOWDEN CABLE COVER	Not Necessary	12.00 FS	*- FS
34	1		*BONNET RELEASE ELEMENT	Not Necessary	73.00 FS	*- FS
35	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	274.00 FS	*216.80 FS
36	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
37	1		*SUNDRIES	Not Necessary	600.00 FS	*- FS
38	1		*FRONT DOOR - RH (Supplementary)	Dented	3,340.00 FS	*2,672.00 FS
39	1		*FRONT DOOR OUTER SEAL - RH (Supplementary)	Necessary	275.00 FS	*220.00 FS
40	1		*FRONT DOOR COVER - RH (Supplementary)	Necessary	445.00 FS	*356.00 FS
41	1		*FRONT LOCK CARRIER (Supplementary)	Cracked	821.00 FS	*656.40 FS
42	1		*FRONT BUMPER REINFORCEMENT BEAM BOTH SUPPORT (Supplementary)	Bent	125.00 FS	*100.00 FS
43	1		*RADIATOR AIR GUIDE CENTER (Supplementary)	Deformed	155.00 FS	*123.60 FS
44	6		*READY MIX-COOLANT 1LITER (Supplementary)	Necessary	332.00 FS	*265.44 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 32,853.00 18,548.64**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS AND OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	500.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, FRONT BUMPER TRIM, BONNET AND BOTH FRONT WHEEL ARCH TRIMS	New	4,500.00	1,800.00
5	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION	New	800.00	0.00
6	TO CARRY OUT DE-ENERGEISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACTIVATION	New	480.00	480.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
8	TO REMOVE AND TRANSFER RHS FRONT DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES (Supplementary)	New	250.00	250.00
9	TO DISMANTLE RENEW FRONT RHS DOOR (Supplementary)	New	500.00	500.00
10	TO RESPRAY RHS FRONT DOOR AND DOOR COVER (Supplementary)	New	750.00	750.00
11	TO REMOVE AND REINSTALL AIRCON CONDENSER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURE COOLING SYSTEM. (Supplementary)	New	1,800.00	1,800.00
12	TO CARRY OUT VACUUM AND REGAS FOR R1234 (Supplementary)	New	1,200.00	1,200.00
13	TO REMOVE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION (Supplementary)	New	1,000.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>15,252.00</b>	<b>9,552.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >