

ASS. REC. BY:

REF:

SPF/ CS/SPF24090252/Kvp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: QX 1748S

Policy No.

Claims No. ACS/105/009/2024/047(CF)

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNS 4009J

Yr Regn:

24

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Sienta

C.C.

1490

Colour

M. White

A/C:

Insured / Std / NI / NA

Sp. Reading

2862

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MXPL10 1120908

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185/85R15

R:

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
TOYO/YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

10/9/24

D.O.I.

10/9/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 SH not ready, Tel you jammed

22/10/24 1 Pm @ 4400k Calm (red 11,321.73, 72%)
repair range \$4400-\$5000

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: TOYOTA SIENTA

Engine/Chassis No.:

Date of accident:

Damaged area: Rear

Not withair

11 Lm @ 4400h

Running After Paint

5 days

Date: 21/09/2024

Claim Type: TP

VRN: SNS 4009J

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate <i>1495</i>	<i>R</i> 1	\$ 2,350.00	\$ 2,350.00
2	Tailgate outer moulding	<i>R</i> 1	\$ 385.00	\$ 385.00
3	Tailgate logo	<i>R</i> 1	\$ 72.20	\$ 72.20
4	Tailgate weatherstrip <i>290</i>	<i>ndtpr</i> 1	\$ 372.30	\$ 372.30
5	Tailgate hybrid emblem	<i>R</i> 1	\$ 83.00	\$ 83.00
6	Antenna buzzer <i>182</i>	<i>CR</i> 1	\$ 269.00	\$ 269.00
7	Tailgate hinge	<i>R</i> 2	\$ 135.00	\$ 270.00
8	Tailgate damper	<i>R</i> 2	\$ 177.00	\$ 354.00
9	Tailgate windscreen moulding <i>112</i>	<i>R</i> 1	\$ 194.00	\$ 194.00
10	Taillamp	<i>R</i> 2	\$ 789.00	\$ 1,578.00
11	Rear bumper side reflector	<i>R</i> 2	\$ 177.00	\$ 354.00
12	Tailgate inner trim	<i>R</i> 1	\$ 297.00	\$ 297.00
13	Rear wheel house n/s	<i>R</i> 1	\$ 994.00	\$ 994.00
14	Rear bumper sensor holder	<i>R</i> 4	\$ 27.00	\$ 108.00
15	Rear bumper <i>585</i>	<i>R</i> 1	\$ 1,150.00	\$ 1,150.00
16	Rear bumper retainer	<i>R</i> 2	\$ 76.00	\$ 152.00
17	Rear bumper bracket	<i>R</i> 2	\$ 68.00	\$ 136.00
18	End panel	<i>R</i> 1	\$ 785.00	\$ 785.00
19	End panel top garnish	<i>R</i> 1	\$ 284.00	\$ 284.00
20	Rear fender inner trim n/s	<i>R</i> 1	\$ 778.40	\$ 778.40
21	Rear licence plate lamp	<i>R</i> 2	\$ 113.90	\$ 227.80
22	Tailgate inner handle	<i>R</i> 1	\$ 86.30	\$ 86.30
23	Taillamp lower bracket	<i>R</i> 2	\$ 49.00	\$ 98.00
24	Tailgate lock <i>310</i>	<i>R</i> 1	\$ 456.40	\$ 456.40
25	Spare tyre panel top board <i>385</i>	<i>CR</i> <i>R</i> 1	\$ 443.90	\$ 443.90
26	Spare tyre panel	<i>R</i> 1	\$ 884.00	\$ 884.00
Subtotal				\$ 13,162.30
List discount				25.00%
Total				\$ 9,871.73

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate windscreen inner seal	<i>R</i> 1	\$ 100.00	\$ 100.00
2	Tailgate windscreen sealant	<i>R</i> 1	\$ 100.00	\$ 100.00
3	Tailgate outer garnish clips	<i>R</i> 6	\$ 5.50	\$ 33.00
4	Spare tyre panel sealant	<i>R</i> 1	\$ 100.00	\$ 100.00

Repair Estimate

5	Tailgate inner trim clips	nn	10	\$ 5.50	\$ 55.00	X
6	Taillamp clips	nn	6	\$ 5.50	\$ 33.00	X
7	End panel top garnish clips	nn	6	\$ 5.50	\$ 33.00	✓
8	End panel sealant	nn	1	\$ 100.00	\$ 100.00	301w
9	Rear licence plate & frame	nn	1	\$ 55.00	\$ 55.00	X
10	Reverse sensor C 245	nn	4	\$ 280.00	\$ 1,120.00	490
11	Rear bumper clips	nn	12	\$ 5.50	\$ 66.00	✓
12	Rear wheel house sealant n/s	nn	1	\$ 100.00	\$ 100.00	X
13	Rear licence plate & frame	nn	1	\$ 55.00	\$ 55.00	X
14	Sundries	nn	1	\$ 50.00	\$ 50.00	X
					Total	\$ 2,000.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	9	\$ 600 1,800.00
2	To disconnect wire harnesses of electrical components to facilitate repairs, reconnect and check functions.	0.5	\$ 200 100.00
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 600 100.00
4	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 1200 150.00
5	Supply spray paint material and necessary items to affected area / panel.	8	\$ 600 1,600.00
6	To rust proof all affected portions after repair.	0.5	\$ 600 100.00
Total labour			\$ 3,850.00

Estimate Grand Total	\$ 15,721.73
-----------------------------	---------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: