

ASS. REC. BY:

REF:

LIP /

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: VLB 3338 Yr Regn: 07, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or AD WagonMake: Proton X90 C.C. 1477Colour: White A/C: Insured / Std / NI / NASp. Reading: 725 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PL1802BVRQG003336

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/50 R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 10/9/24 D.O.I. 19/9/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

all body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Est not ready, acc report not ready19/11 21 Rm 84400k Cash

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

NOT Withheld
 11 Days & 440ph
 Recovery After Painting
 5 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : VLB 3338

Acc: 10.9.24

S/N Parts Description

- 1 Front door LH
- 2 Front door LH lock
- 3 Front door regulator and motor LH
- 4 Front door rubber LH
- 5 Front door protector LH
- 6 Front door protector mldg LH
- 7 Front door emblem LH
- 8 Rear door LH
- 9 Rear door lock LH
- 10 Rear door regulator and motor LH
- 11 Rear door rubber LH
- 12 Rear door protector LH
- 13 Rear door protector mldg LH
- 14 Rear fender protector LH
- 15 Rear bumper
- 16 Rear wheel rim LH

Unit Price Amt

R	\$1,090	✓
R	\$380.00	X
R	\$580.00	X
R	\$255.00	X
Rd/Lm	\$392.00	—
R	\$148.00	—
R	\$72.00	—
R	\$1,052.00	✓
R	\$368.00	X
R	\$542.00	X
R	\$235.00	X
Rd/Lm	\$365.00	✓
R	\$138.00	—
R	\$218.00	—
Sen R	\$1,011.00	X
Rd/Lm	\$905.00	✓

108

Labour

- 1 To remove and refit damaged parts
- 2 To spray paint on affected parts
- 3 To transfer both LH doors mechanism
- 4 Wheel alignment
- 5 Tuff coat on affected parts

\$1,000.00	5506
\$1,200.00	8006
\$200.00	1201
\$120.00	601
\$150.00	601

Page 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: