

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090256/APA3Q2**Date:** 07/02/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800156119
Claimant Vehicle No :	SGM5870X	Insured Vehicle No :	SMN9391J
Date of Loss:	05/09/2024	Nature of Claim:	TP
		Claim No:	0247349249SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGM5870X		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT ABS D/AIRBAG 2WD (A)	Engine No:	L15B3537221
Reg. Date:	13/10/2016 (Man. Year: 2016)	Chassis No:	GK81006148
Colour:	Silver	Odometer:	169303 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,636.88	6,801.04	5,835.84	46.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	1,680.00	2,380.00	58.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,696.88	8,481.04	8,215.84	49.21
Approved Total (Overridden) (S\$)		6,750.00		
(S\$)	16,696.88	6,750.00	9,946.88	59.57
+ GST 9.00/9.00% (S\$)	1,502.72	607.50	895.22	59.57
Nett Amount (S\$)	18,199.60	7,357.50	10,842.10	59.57
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		7,884.75		

INSPECTION

Date of Assignment:	29/09/2024	
Date Inspected:	29/09/2024	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	1,193.40 FL	*1,193.40 FL
2	1		*TAIL GATE OUTER GARNISH C/W MOULDING (CHROME)	Not Necessary	685.10 FL	*- FL
3	1		*TAIL GATE REVERSE CAMERA	Not Necessary	1,352.00 FL	*- FL
4	1		*TAIL GATE LOGO	Not Necessary	38.20 FL	*- FL
5	1		*TAIL GATE EMBLEM SHUTTLE	Necessary	55.70 FL	*55.70 FL
6	2		*TAIL GATE LAMP	Cut	790.00 FL	*790.00 FL
7	2		*TAIL GATE DAMPER	Not Necessary	208.20 FL	*- FL
8	1		*TAIL GATE INNER HOLDER	Not Necessary	27.50 FL	*- FL
9	2		*TAIL GATE STOPPER	Not Necessary	38.00 FL	*- FL
10	1		*TAIL GATE LOCK CATCH	Not Necessary	24.00 FL	*- FL
11	1		*TAIL GATE WEATHERSTRIP	Cut	168.10 FL	*168.10 FL
12	1		*TAIL GATE DETECTOR	Not Necessary	296.00 FL	*- FL
13	1		*TAIL GATE DETECTOR WIRE HARNESS	Not Necessary	436.40 FL	*- FL
14	1		*TAIL GATE INNER TRIM	Cracked	320.00 FL	*320.00 FL
15	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	150.10 FL	*150.10 FL
16	1		*REAR BUZZER	Not Necessary	124.30 FL	*- FL
17	2		*TAIL LAMP	Cut	1,041.00 FL	*1,041.00 FL
18	2		*TAIL LAMP LOWER PANEL	Dented	470.40 FL	*470.40 FL
19	2		*REAR FENDER COWLING	Not Necessary	295.00 FL	*- FL
20	1		*REAR FENDER INNER TRIM	O/S Cracked	1,100.00 FL	*349.00 FL
21	1		*REAR BUMPER	Deformed	1,150.60 FL	*985.00 FL
22	2		*REAR BUMPER REFLECTOR	Not Necessary	87.60 FL	*- FL
23	2		*REAR BUMPER REFLECTOR GARNISH	Not Necessary	90.20 FL	*- FL
24	1		*REAR BUMPER TOWING COVER	Missing	19.00 FL	*19.00 FL
25	2		*REAR BUMPER SIDE INNER GARNISH	Not Necessary	196.80 FL	*- FL
26	2		*REAR BUMPER SIDE RETAINER	Not Necessary	53.00 FL	*- FL
27	2		*REAR BUMPER SIDE BRACKET	Not Necessary	48.00 FL	*- FL
28	2		*REAR BUMPER SPONGE	Cracked	94.00 FL	*94.00 FL
29	1		*REAR END PANEL	Dented	685.10 FL	*685.10 FL
30	1		*REAR END PANEL TOP GARNISH	Deformed	155.50 FL	*155.50 FL
31	1		*REAR FLOOR PANEL TOP OUTER BOARD	Deformed	585.00 FL	*585.00 FL
32	2		*REAR FLOOR PANEL TOP SIDE BOARD	Not Necessary	300.00 FL	*- FL
33	1		*REAR STORAGE BOX (SPONGE)	Not Necessary	185.40 FL	*- FL
34	1		*REAR STORAGE BOX (PLASTIC)	Cracked	495.00 FL	*395.00 FL
35	1		*REAR TOOLS SPONGE TRAY	Not Necessary	185.00 FL	*- FL
36	1		*REAR JACK COVER GARNISH	Deformed	190.00 FL	*190.00 FL
37	1		*REAR JACK	Not Necessary	145.00 FL	*- FL
38	1		*TAIL GATE INNER LOCK	Damaged	180.00 FL	*180.00 FL
39	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
40	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
41	1		*SET TAIL GATE OUTER GARNISH CLIP	Not Necessary	40.00 FS	*- FS
42	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	60.00 FS	*30.00 FS
43	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
44	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
45	1		*SET TAIL LAMP CLIP	Not Necessary	40.00 FS	*- FS
46	2		*TAIL LAMP LOWER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
47	1		*SET SET REAR FENDER INNER COWLING	Not Necessary	80.00 FS	*- FS
48	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	80.00 FS	*30.00 FS
49	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
50	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*20.00 FS
51	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
52	4		*REVERSE SENSOR	Damaged	480.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 15,368.60 8,366.30

- List Item Discount on L Items 20.00/20.00% (\$\$) 2,731.72 1,565.26

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	12,636.88	6,801.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVAL AND REPLACING PARTS (REAR)	New	1,800.00	700.00
2	TO SPRAY PAINT AFFECTED AREA (REAR)	New	1,600.00	700.00
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING (REAR)	New	80.00	50.00
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING (REAR)	New	80.00	50.00
5	REMOVE AND REFIX TAILGATE WINDSCREEN (REAR)	New	120.00	120.00
6	TRANSFER TAILGATE MECHANISM (REAR)	New	80.00	60.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC (REAR)	New	300.00	0.00
			Gross Labour Cost (\$\$)	4,060.00
				1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >