


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 09.09.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SGM5870X**
MODEL : **HONDA SHUTTLE**
DATE OF ACCIDENT : 05.09.2024
TIME OF ACCIDENT : 08:20 HOURS

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Detent</i>	1	\$ 1,193.40	\$ 1,193.40
2	TAIL GATE OUTER GARNISH CW MOULDING (CHROME)	1	\$ 685.10	\$ 685.10
3	TAIL GATE REVERSE CAMERA <i>new</i>	1	\$ 1,352.00	\$ 1,352.00
4	TAIL GATE LOGO <i>new</i>	1	\$ 38.20	\$ 38.20
5	TAIL GATE EMBLEM SHUTTLE' <i>new</i>	1	\$ 55.70	\$ 55.70
6	TAIL GATE LAMP <i>cut</i>	2	\$ 395.00	\$ 790.00
7	TAIL GATE DAMPER <i>new</i>	2	\$ 104.10	\$ 208.20
8	TAIL GATE INNER HOLDER <i>new</i>	1	\$ 27.50	\$ 27.50
9	TAIL GATE STOPPER <i>new</i>	2	\$ 19.00	\$ 38.00
10	TAIL GATE INNER LOCK <i>new</i>	1	\$ 180.00	\$ 180.00
11	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 24.00	\$ 24.00
12	TAIL GATE WEATHER STRIP <i>cut</i>	1	\$ 168.10	\$ 168.10
13	TAIL GATE DETECTOR <i>new</i>	1	\$ 296.00	\$ 296.00
14	TAIL GATE DETECTOR WIRE HARNESS <i>new</i>	1	\$ 436.40	\$ 436.40
15	TAIL GATE INNER TRIM <i>cut</i>	1	\$ 320.00	\$ 320.00
16	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 150.10	\$ 150.10
17	REAR BUZZER <i>new</i>	1	\$ 124.30	\$ 124.30
18	TAIL LAMP <i>cut</i>	2	\$ 520.50	\$ 1,041.00
19	TAIL LAMP LOWER PANEL <i>new Detent</i>	2	\$ 235.20	\$ 470.40
20	REAR FENDER COWLING <i>new</i>	2	\$ 147.50	\$ 295.00
21	REAR FENDER INNER TRIM <i>RH cut</i>	2	\$ 550.00	\$ 1,100.00

Handwritten notes and markings on the right side of the table, including checkmarks, plus signs, and a circled '349' at the bottom.

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SGM5870X**
 MODEL : **HONDA SHUTTLE**
 DATE OF ACCIDENT : 05.09.2024
 TIME OF ACCIDENT : 08:20 HOURS

13	REAR FLOOR PANEL INSULATION SEAL <i>den</i>	1	\$ 350.00	\$ 350.00
14	REVERSE SENSOR(4PCS) <i>den</i>	1	\$ 480.00	\$ 480.00

+
300

540

TOTAL \$ 1,710.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	700
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	700
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
6	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 300.00	+

1680

TOTAL 4060

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,636.88
 TOTAL LABOUR COST : \$ 4,060.00
 TOTAL REPAIR COST : \$ 16,696.88

Adrian Ly
h/s 09/09/24

062m

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

total: 8481.04

h/s: 6150 ✓

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP :8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: