

ASSIGNMENT

FRONT: _____ Date: _____
 Estin: _____
 OD / TP RES / OD RES / EVA / INV / MV
 To in _____ Vehicle No: _____
 at _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client Record)
 Make of Vehicle: _____
 (Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SGM5870X Yr Regn: 2016, Oct.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Azuda Shuttle C.D. 1496
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 169303 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GK81006148
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 29/09/24
 Survey held at HD Perfect
 Des. of Damages: Frit / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP ALG</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV: Yes (✓)</u>
	<u>PV: No ()</u>
	<u>Nett:</u>
	<u>266B.</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Form ref: _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Inve (\$ _____)

Survey Fee: _____
 Transportation: _____
 \$ + R.S. \$ _____
 Photos _____
 Others _____


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 09.09.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SGM5870X**
MODEL : HONDA SHUTTLE
DATE OF ACCIDENT : 05.09.2024
TIME OF ACCIDENT : 08:20 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented</i>	1	\$ 1,193.40	\$ 1,193.40
2	TAIL GATE OUTER GARNISH C/W MOULDING (CHROME)	1	\$ 685.10	\$ 685.10
3	TAIL GATE REVERSE CAMERA <i>new</i>	1	\$ 1,352.00	\$ 1,352.00
4	TAIL GATE LOGO <i>new</i>	1	\$ 38.20	\$ 38.20
5	TAIL GATE EMBLEM SHUTTLE' <i>new</i>	1	\$ 55.70	\$ 55.70
6	TAIL GATE LAMP <i>cut</i>	2	\$ 395.00	\$ 790.00
7	TAIL GATE DAMPER <i>new</i>	2	\$ 104.10	\$ 208.20
8	TAIL GATE INNER HOLDER <i>new</i>	1	\$ 27.50	\$ 27.50
9	TAIL GATE STOPPER <i>new</i>	2	\$ 19.00	\$ 38.00
10	TAIL GATE INNER LOCK <i>new</i>	1	\$ 180.00	\$ 180.00
11	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 24.00	\$ 24.00
12	TAIL GATE WEATHER STRIP <i>cut</i>	1	\$ 168.10	\$ 168.10
13	TAIL GATE DETECTOR <i>new</i>	1	\$ 296.00	\$ 296.00
14	TAIL GATE DETECTOR WIRE HARNESS <i>new</i>	1	\$ 436.40	\$ 436.40
15	TAIL GATE INNER TRIM <i>cut</i>	1	\$ 320.00	\$ 320.00
16	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 150.10	\$ 150.10
17	REAR BUZZER <i>new</i>	1	\$ 124.30	\$ 124.30
18	TAIL LAMP <i>cut</i>	2	\$ 520.50	\$ 1,041.00
19	TAIL LAMP LOWER PANEL <i>new Dented</i>	2	\$ 235.20	\$ 470.40
20	REAR FENDER COWLING <i>new</i>	2	\$ 147.50	\$ 295.00
21	REAR FENDER INNER TRIM <i>RH cut</i>	2	\$ 550.00	\$ 1,100.00

Handwritten notes and markings on the right side of the table, including checkmarks, plus signs, and a circled '550' at the bottom.

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SGM5870X**
 MODEL : HONDA SHUTTLE
 DATE OF ACCIDENT : 05.09.2024
 TIME OF ACCIDENT : 08:20 HOURS

22	REAR BUMPER <i>Delat</i>	1	\$ 1,150.60	\$ 1,150.60	985
23	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 43.80	\$ 87.60	+
24	REAR BUMPER REFLECTOR GARNISH <i>new</i>	2	\$ 45.10	\$ 90.20	+
25	REAR BUMPER TOWING COVER <i>Missing</i>	1	\$ 19.00	\$ 19.00	-
26	REAR BUMPER SIDE INNER GARNISH	2	\$ 98.40	\$ 196.80	+
27	REAR BUMPER SIDE RETAINER <i>Ja</i>	2	\$ 26.50	\$ 53.00	+
28	REAR BUMPER SIDE BRACKET <i>Ja</i>	2	\$ 24.00	\$ 48.00	+
29	REAR BUMPER SPONGE <i>Crack</i>	2	\$ 47.00	\$ 94.00	✓
30	REAR END PANEL <i>Dented</i>	1	\$ 685.10	\$ 685.10	✓
31	REAR END PANEL TOP GARNISH <i>Delat</i>	1	\$ 155.50	\$ 155.50	✓
32	REAR FLOOR PANEL TOP OUTER BOARD <i>Delat</i>	1	\$ 585.00	\$ 585.00	✓
33	REAR FLOOR PANEL TOP SIDE BOARD <i>new</i>	2	\$ 150.00	\$ 300.00	+
34	REAR STORAGE BOX (SPONGE) <i>new</i>	1	\$ 185.40	\$ 185.40	+
35	REAR STORAGE BOX (PLASTIC) <i>Crack</i>	1	\$ 495.00	\$ 495.00	✓
36	REAR TOOLS SPONGE TRAY <i>new</i>	1	\$ 185.00	\$ 185.00	+
37	REAR JACK COVER GARNISH <i>Delat</i>	1	\$ 190.00	\$ 190.00	✓
38	REAR JACK <i>new</i>	1	\$ 145.00	\$ 145.00	+

TOTAL PRICE \$ 13,658.60
 LESS 20% \$ 2,731.72
SUB TOTAL PRICE \$ 10,926.88

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	TAIL GATE OUTER GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
4	TAIL GATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	30
5	TAIL GATE WINDSCREEN SEALANT <i>Ja</i>	1	\$ 80.00	\$ 80.00	40
6	TAIL GATE WINDSCREEN INNER SEAL <i>Ja</i>	1	\$ 60.00	\$ 60.00	30
7	TAIL LAMP CLIP (SET) <i>Ja</i>	1	\$ 40.00	\$ 40.00	+
8	TAIL LAMP LOWER PANEL SEALANT <i>Ja</i>	2	\$ 60.00	\$ 120.00	+
9	REAR FENDER INNER COWLING (SET) <i>Ja</i>	1	\$ 80.00	\$ 80.00	+
10	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
11	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
12	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	20

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SGM5870X**
 MODEL : **HONDA SHUTTLE**
 DATE OF ACCIDENT : 05.09.2024
 TIME OF ACCIDENT : 08:20 HOURS

13	REAR FLOOR PANEL INSULATION SEAL <i>den</i>	1	\$ 350.00	\$ 350.00
14	REVERSE SENSOR(4PCS) <i>Revd</i>	1	\$ 480.00	\$ 480.00

+
300

TOTAL \$ 1,710.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	<i>700</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	<i>700</i>
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>
5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>
6	TRANSFER TAILGATE MECHANISM	\$ 80.00	<i>-60</i>
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 300.00	<i>+</i>

TOTAL 4060

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,636.88
 TOTAL LABOUR COST : \$ 4,060.00
 TOTAL REPAIR COST : \$ 16,696.88

Advised by
H/S 09/09/24
06277

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP :8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: