

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CS/AIG24090257/ANP3M4(N)  
**Date:** 07/01/2025**REFERENCE**Insured/Claimant: **ONG YONG WEN (WONG YONGWEN)** Policy No: 7230114772  
Date of Loss: 13/09/2024 Nature of Claim: OD Claim No: 8349476315SG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMA7308H**  
Make & Model: AUDI A3, 999cc SEDAN 1.0 TFSI S TRONIC (A) Engine No: DLAE21699  
Reg. Date: 29/11/2023 (Man. Year: 2022) Chassis No: WAUZZZGY3NA101111  
Colour: Grey Odometer: 16762 km  
Engine Capacity: 999 cc  
Market Value/New Car Price: S\$170,000.00  
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:**CONDITION OF TYRES**Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,697.00	1,782.08	1,914.92	51.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,152.00	1,702.00	1,450.00	46.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,849.00</b>	<b>3,484.08</b>	<b>3,364.92</b>	<b>49.13</b>
<b>+ GST 9.00/9.00% (S\$)</b>	616.41	313.57	302.84	49.13
<b>Nett Amount (S\$)</b>	<b>7,465.41</b>	<b>3,797.65</b>	<b>3,667.76</b>	<b>49.13</b>

**INSPECTION**Date of Assignment: 16/09/2024  
Date Inspected: 16/09/2024 Inspected At: PREMIUM AUTOMOBILES PTE LTD (UBI)  
55 UBI ROAD 1  
SINGAPORE 408699  
Estimated Period of Repair: 3.0 days**Adjuster:** ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,894.00 FS	*1,515.20 FS
2	2		*REAR BUMPER LOCKING MECHANISM - LH / RH	Not Necessary	36.00 FS	*- FS
3	1		*REAR BUMPER TRIM - LH	Cut	81.00 FS	*64.08 FS
4	1		*REAR PARKING AID SENSOR SUPPORT - LH OUTER	Not Necessary	32.00 FS	*- FS
5	1		*REAR BUMPER AIR GUIDE GRILLE SENSOR - LH	Not Necessary	300.00 FS	*- FS
6	1		*REAR BUMPER SPOILER	Cut	254.00 FS	*202.80 FS
7	1		*REAR LIGHT REFLECTOR - LH	Not Necessary	41.00 FS	*- FS
8	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	689.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	70.00 FS	*- FS
10	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)**      **3,697.00**      **1,782.08**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
3	TO RESPRAY REAR BUMPER	New	1,100.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,152.00</b>	<b>1,702.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >