

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24090258/KNP3E2**Date:** 24/09/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SKZ8013T **Insured Vehicle No :** SNG1751G

Date of Loss: 12/09/2024 Nature of Claim: TP Claim No: DMCF2400061H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ8013T**

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4030310

Reg. Date: 03/02/2016 (Man. Year: 2015) Chassis No: RU11110307

Colour: Metallic Pearl White Odometer: 184272 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55ZR17 Rear Tyre Size: 215/55ZR17

Front Left Side: Kumho 8 mm Rear Left Side: Kumho 7 mm

Front Right Side: Kumho 8 mm Rear Right Side: Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,731.20	2,874.84	2,856.36	49.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,610.00	1,380.00	1,230.00	47.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,341.20	4,254.84	4,086.36	48.99
Approved Total (Overridden) (S\$)		3,400.00		
Nett Amount (S\$)	8,341.20	3,400.00	4,941.20	59.24

INSPECTION

Date of Assignment: 16/09/2024

Date Inspected: 16/09/2024 Inspected At: Guan Motor Works (HQ)
176 Sin Ming Drive #02-03 Sin Ming Autocare
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2024)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ8013T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	571.80 F	*571.80 FL
2	2		*REAR BUMPER SIDE REFLECTOR	Serviceable	170.80 F	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Serviceable	96.00 F	*- FL
4	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	2		*REAR CORNER COVER	Serviceable	345.60 F	*- FL
6	2		*REAR CORNER COVER RETAINER	Serviceable	72.00 F	*- FL
7	1		*REAR TAILGATE	Bent	1,290.00 F	*1,099.20 FL
8	1		*REAR TAILGATE LH VEZEL EMBLEM	Necessary	48.00 F	*48.00 FL
9	1		*REAR TAILGATE TOP LOCK	Dented	121.00 F	*121.00 FL
10	1		*REAR TAILGATE LOWER LOCK CATCH	Repair	34.00 F	*- FL
11	1		*REAR TAILGATE INNER TRIM BOARD	Mtg Distorted	285.00 F	*285.00 FL
12	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 F	*60.00 FL
13	1		*REAR END PANEL	Bent	399.40 F	*399.40 FL
14	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	192.30 F	*192.30 FL
15	1		*REAR END PANEL KEYLESS SENSOR	Dented	195.30 F	*88.10 FL
16	1		*REAR END PANEL BUZZER	Serviceable	65.70 F	*- FL
17	1		*REAR SPARE TYRE TOP BOARD	Serviceable	228.70 F	*- FL
18	1		*REAR UNDER SPLASH COVER	Cracked	290.00 F	*269.00 FL
19	1		*REAR TAILGATE WEATHERSTRIP (50%)	Dented / Distorted	115.60 FS	*57.80 FS
20	1		*SET REVERSE SENSORS	Shorted	280.00 FS	*200.00 FS
21	1		*SET REVERSE CAMERA	Serviceable	650.00 FS	*- FS
22	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
23	1		*SET REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
24	1		*SET REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,731.20	3,511.60
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	636.76
Total Parts (\$\$)	5,731.20	2,874.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REMOVE/REFIT,CUTTING/WELDING AND REPLACEMENT OF DAMAGES	New	1,000.00	600.00
2	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
3	TO REMOVE,REFIT REAR WINDSCREEN GLASS	New	140.00	120.00
4	TO REMOVE,REFIT REVERSE SENSORS & REVERSE CAMERA	New	150.00	60.00
5	TO REMOVE,REFIT TAILGATE FITTINGS	New	80.00	60.00
6	TO REMOVE,REFIT REAR UPHOLSTERY AND ATTACHMENTS	New	120.00	60.00
7	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	60.00
8	TO PUTTY AND SPRAY PAINTINGS CHARGES	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,610.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >