



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHC 1850X

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER ASSY	DEFORMED	\$459.40	\$459.40
10	REAR BUMPER CLIPS	NECESSARY	\$22.00	\$22.00
1	REAR BUMPER CENTRE MOULDING	DEFORMED	\$451.25	\$451.25
1	REAR BUMPER BEAM	NOT NECESSARY	\$394.80	\$0.00
1	FOG LAMP REAR	NOT NECESSARY	\$201.50	\$0.00
1	ANTENNA SMARTKEY	NOT NECESSARY	\$40.50	\$0.00
	LESS 20.00% DISCOUNT		(\$313.89)	(\$186.53)
			\$1,255.56	\$746.12

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER MAT (SN)	NECESSARY	\$50.00	\$50.00
1	REVERSE SENSOR (SN)	NOT WORKING	\$180.00	\$180.00
1	REAR NUMBER PLATE (SN)	CRACKED	\$55.00	\$55.00
			\$285.00	\$285.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING		\$400.00	\$380.00
	SPRAY PAINT		\$300.00	\$280.00
	REMOVE / REFIX REVERSE SENSOR		\$50.00	\$30.00
			\$750.00	\$690.00

GRAND TOTAL	\$2,290.56	\$1,721.12
--------------------	-------------------	-------------------

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	\$1,400.00
---	-------------------

Report Ref No: CS/UOI24090259/Tvp3e2

MTH

MOHAMAD TAUFIKH



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.