COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

SHC1850X

MAKE MODEL

HYUNDAI

IONIQ

DATE:

13.09.34

MVA

JUMANI

DOA:

12.09.24

UOI

ODEL	IUNIQ	DOA.	12.03.27	
Qty	Parts Description/ Labour	Туре	7.23	Amount
	1 REAR BUMPER ASSY			\$459.404/
1	REAR BUMPER CLIPS			\$22.00
	1 REAR BUMPER CENTRE MOULDING			\$451.25
	1 REAR BUMPER BEAM			\$394.80
	1 FOG LAMP REAR			\$201.50
:	I ANNTENNA SMARTKEY			\$40.50
	SUB TOTAL		932.65	\$1,569.45
	LESS 20%		746.12	\$313.89
	DISCOUNTED TOTAL		77617	\$1,255.56
	REAR BUMPER MAT			\$50.00 NE
	REVERSE SENSOR		76	\$180.00 NE
	REAR NUMBER PLATE			a / \$55.00 NE
	DIS 10%		285	
	SUB TOTAL			\$285.00 NE
	Labour Charge			
	PANEL BEATING		[00	\$8~ \$400.00
	SPRAY PAINT		690	280 \$300.00
	REMOVE/REFIX REVERSE SENOR			50 \$50.00
			1771.12	
	TOTAL LABOUR		1721:12 4591400 02days	\$750.00
			4541400	
	ESTIMATE TOTAL		9.1.	
			02days	\$2,290.56
			≫ \	
	ÿs.			
	his is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will			
	e prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			
	e prepared after the vehicle is surveyed by a motor surveyor appointed by the metallic company			

Les Permanger report tagin e likhants. m

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Projudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurence Company

Acknowledged by Repairer

Signature:

Date: