

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090260/UMA3Q2**Date:** 12/12/2024**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7230086328
Claimant Vehicle No :	PC2575P	Insured Vehicle No :	SMF925X
Date of Loss:	12/09/2024	Nature of Claim:	TP
		Claim No:	5115437771SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC2575P		
Make & Model:	TOYOTA HIACE, 3.0 D HIGH ROOF COMMUTER TURBO (A)	Engine No:	1KD2384385
Reg. Date:	11/04/2014 (Man. Year: 2014)	Chassis No:	JTFST22P600019441
Colour:	White	Odometer:	678576 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,588.47	8,522.65	10,065.82	54.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,110.00	2,140.00	2,970.00	58.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,698.47	10,662.65	13,035.82	55.01
Approved Total (Overridden) (S\$)		8,500.00		
(S\$)	23,698.47	8,500.00	15,198.47	64.13
+ GST 9.00/9.00% (S\$)	2,132.86	765.00	1,367.86	64.13
Nett Amount (S\$)	25,831.33	9,265.00	16,566.33	64.13
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.18		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		10,117.18		
Global Sum Settlement (S\$)		10,100.00		

INSPECTION

Date of Assignment:	16/09/2024	
Date Inspected:	16/09/2024	Inspected At: Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	8.0 days	

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,022.10 FL	*- FL
2	2		*BONNET HINGES	Not Necessary	190.00 FL	*- FL
3	1		*BONNET LOCK	Not Necessary	166.80 FL	*- FL
4	1		*BONNET LOGO	Serviceable	105.00 FL	*- FL
5	1		*SET BONNET INSULATOR CLIPS	Not Necessary	150.00 FL	*- FL
6	1		*FRONT GRILLE TOP	Cracked	481.00 FL	*481.00 FL
7	1		*FRONT GRILLE LOWER	Repair	655.10 FL	*- FL
8	1		*FRONT SUPPORT TOP PANEL	Repair	755.10 FL	*- FL
9	1		*BRACE BRACKET	Not Necessary	151.10 FL	*- FL
10	1		*WIPER WASHER TANK	Not Necessary	332.10 FL	*- FL
11	1		*FRONT BUMPER	Distorted	865.10 FL	*781.10 FL
12	1		*FRONT BUMPER SIDE HOLDER N/S	Cracked	166.50 FL	*166.50 FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
14	1		*FRONT BUMPER TOP BEAM	Serviceable	321.00 FL	*- FL
15	1		*FRONT BUMPER BEAM	Bent	655.20 FL	*655.20 FL
16	1		*FRONT BUMPER BEAM BRACKET N/S	Bent	250.00 FL	*250.00 FL
17	1		*FRONT BUMPER FOG LAMP COVER N/S	Twisted	145.20 FL	*145.20 FL
18	1		*FRONT BUMPER CENTRE GRILLE	Twisted	144.20 FL	*144.20 FL
19	1		*FRONT TOW COVER	Missing	28.00 FL	*28.00 FL
20	1		*HEADLAMP N/S	Cracked	1,075.20 FL	*1,075.20 FL
21	1		*HEADLAMP O/S	Not Necessary	1,075.20 FL	*- FL
22	1		*FRONT DOOR N/S	Badly Dented	1,788.20 FL	*1,788.20 FL
23	1		*FRONT DOOR OUTER PILLAR N/S	Badly Dented	1,099.20 FL	*1,099.20 FL
24	1		*FRONT DOOR HINGES N/S	Lower Bent /Twisted	210.00 FL	*105.00 FL
25	1		*FRONT DOOR CHECKER N/S	Twisted	165.00 FL	*165.00 FL
26	1		*FRONT DOOR INNER RUBBER N/S	Torn	229.10 FL	*229.10 FL
27	1		*FRONT DOOR GLASS REGULATOR N/S	Bent	366.50 FL	*366.50 FL
28	1		*FRONT DOOR GLASS REGULATOR MOTOR N/S	Jammed	680.10 FL	*680.10 FL
29	1		*FRONT DOOR INNER TRIM BOARD N/S	Deformed / Torn	699.20 FL	*699.20 FL
30	1		*FRONT DOOR GLASS OUTER MOULDING N/S	Bent	122.20 FL	*122.20 FL
31	1		*FRONT DOOR INNER CHANNEL RUBBER N/S	Twisted	288.90 FL	*288.90 FL
32	1		*FRONT STEP GARNISH N/S	Distorted	341.50 FL	*341.50 FL
33	1		*FRONT STEP PANEL N/S	Badly Dented	488.90 FL	*322.20 FL
34	1		*FRONT ARCH PANEL N/S	Repair	651.90 FL	*- FL
35	1		*FRONT WIRE HARNESS N/S	Cracked	950.50 FL	*381.50 FL
36	1		*FRONT WIRE HARNESS BRACKET N/S	Cracked	255.20 FL	*255.20 FL
37	1		*FRONT CORNER PANELS	N/S Bent / O/S Not Necessary	900.00 FL	*450.00 FL
38	1		*CONDENSER	Not Necessary	1,655.20 FL	*- FL
39	1		*FRONT FLOOR PANEL	Repair	2,021.20 FL	*- FL
40	1		*FRONT ARCH PANEL N/S	Repeated	552.20 FL	*- FL
41	1		*FRONT LOWER ARM N/S	Not Necessary	699.60 FL	*- FL
42	1		*FRONT KNUCKLE ARM N/S	Not Necessary	622.80 FL	*- FL
43	1		*FRONT WHEEL HUB BEARING N/S	Not Necessary	480.00 FL	*- FL
44	1		*FRONT TYRE N/S (60%)	Cut	200.00 FS	*120.00 FS
45	1		*FRONT RIM N/S	Serviceable	200.00 FS	*- FS
46	1		*FRONT WHEEL HUB CAP N/S	Cut	150.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,601.30	11,290.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	6,012.83	2,767.55
Total Parts (\$\$)	18,588.47	8,522.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	100.00	60.00
3	TO TRANSFER FRONT DOOR MECHANISM	New	100.00	50.00
4	TO DISMANTLE & REFIX DASHBOARD	New	280.00	0.00
5	TO REFILL AIR CON GAS	New	180.00	0.00
6	TO R&R MASTER BOSTER PUMP	New	100.00	0.00
7	TO RESET & REPROGRAMME SYSTEM	New	120.00	0.00
8	TO CONDUCT WHEEL ALIGNMENT	New	100.00	60.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,280.00	1,000.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	950.00
Gross Labour Cost (\$\$)			5,110.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >