

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24090267/UVP3M4**Date:** 19/11/2024**REFERENCE**

Handling Insurer: ECICS Limited Policy No: MPC24P00157900
Claimant Vehicle No : SMH8304A **Insured Vehicle No :** SKW4582J
 Date of Loss: 11/09/2024 Nature of Claim: TP Claim No: DMPC2401208H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH8304A**
 Make & Model: HONDA HR-V, 1.5 DX CVT (A) Engine No: L15B5671038
 Reg. Date: 11/02/2019 (Man. Year: 2018) Chassis No: JHMRU1810JX201036
 Colour: Brown Odometer: 66496 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55R17 Rear Tyre Size: 215/55R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,113.70	364.24	1,749.46	82.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	600.00	730.00	54.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,443.70	964.24	2,479.46	72.00
Approved Total (Overridden) (S\$)		750.00		
Nett Amount (S\$)	3,443.70	750.00	2,693.70	78.22

INSPECTION

Date of Assignment: 16/09/2024
 Date Inspected: 20/09/2024 Inspected At: SUPER-ZEE MOTOR SERVICE (HQ)
 BLK 14 DEFU LANE 10, #01-402
 SINGAPORE 539195
 Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Nov 2024)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH8304A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	650.80 F	*- FL
2	1		*REAR BUMPER RETAINER RH	Not Necessary	32.40 F	*- FL
3	1		*REAR BUMPER CORNER SIDE RH	Cut/Deformed	218.40 F	*218.40 FL
4	10		*REAR BUMPER CLIPS	Not Necessary	65.00 F	*- FL
5	1		*REAR FENDER ARCH RH	Cut	236.90 F	*236.90 FL
6	1		*REAR FENDER INNER SHIELD RH	Not Necessary	160.20 F	*- FL
7	1		*REAR TYRE RIM RH (CUT)	Not Consistent With The Impact	450.00 FS	*- FS
8	1		*REAR TYRE RH	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	2,113.70 455.30
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 91.06
					Total Parts (\$\$)	2,113.70 364.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	New	550.00	200.00
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT AFFECTED PORTION	New	600.00	400.00
3	TO APPLY RUSTPROOFING ON REPAIRED, REPLACED PANEL	New	180.00	0.00
Gross Labour Cost (\$\$)			1,330.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >