

ASS. REC. BY:

REF:

MSG/ C9/MSG24060163/Kqh3

C

Kenneth

ASSIGNMENT

GRB

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

EM not ready

11/7 11pm @ 12001 Conker Uland @ 1175, 49%

Date/Time, File Pass to?

1) 01/7 11am

Date/Time, File Return to?

2)

Prell. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

7P

1200



SINGAPORE POLICE FORCE



E/20240615/7002

1 of 1

Report No. E/20240615/7002

POLICE REPORT (NP299)

Police Station Of Origin
Tanglin Division HQ
21 Kampong Java Road SINGAPORE
228892
Tel No:1800-3910000

Date/Time Report Made 15/06/2024 08:28	Vide Report No.	Station Diary No.
Name Of Informant Lim Ching Leong	Address 449 CHOA CHU KANG AVENUE 4 #15-449 SINGAPORE 680449	
ID Type / ID No. NRIC NO / S7274416J	Contact No. Home/Office: Mobile: 94506236	
Nationality SINGAPORE CITIZEN	Email Address michael_lim@yahoo.com	
Occupation Electrical engineer	Sex Male	Age 52
Institution/School Name	Date of Birth 13/06/1972	Race Chinese
	Language English	
Date/Time Of Incident 14/06/2024 13:50 - 15/06/2024 08:21	Location Of Incident Blk 275 Bangkit Rd carpark	

Brief details.

My van park at carpeak lot , work after i come back found that my van side single light crack .

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 15/06/2024 08:28
Officer In-Charge Of Case:	Classification Of Case:

This report is lodged at Bukit Timah NPC Kiosk 1



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: silt11@singnet.com.sg Regn. No. 05396600K

LIM BROTHERS MAINTENANCE
BLK 449 CHOA CHU KANG AVE 4
#15-169
SINGAPORE 680449

Dear sir

Estimate cost of repair to vehicle no. GBL5265H

To supply

1. Tail lamp left
2. Sticker 70km
3. Tail gate badge GL n sticker 750
4. Tail gate logo
5. Tail gate
6. Rear bumper

Pro	380.00	✓
M	25.00	150n
M	65.00	✓
M	45.00	✓
B	580.00	✓
M R B	280.00	✗

Labour charges

Rustproofing
Panel beating
Spray painting
Total

100.00	30l
300.00	250l
600.00	400l
2,375.00	

Your faithfully

ALBERT POON

NOT Withdraw
11 Sep @ 1200h
McKinnay After Paint
3 days

LIM Auto Consultants please notify
the repairer of the following:

- To resurvey before/after spray painting
- To display damaged panels during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- If any modification is allowed
- Supplemental survey must be performed and
is subject to final approval from Insurance Company

Forwards by fax to:

Signature:

Date: