



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBL 5265H

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TAIL LAMP LEFT	BROKEN	\$380.00	\$380.00
1	TAIL GATE BADGE GL N STICKER 750	NECESSARY	\$65.00	\$65.00
1	TAIL GATE LOGO	NECESSARY	\$45.00	\$45.00
1	TAIL GATE	BENT	\$580.00	\$580.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	\$280.00	\$0.00
	LESS 0.00 / 25.00% DISCOUNT		\$0.00	(\$267.50)
			\$1,350.00	\$802.50
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	STICKER 70KM (SN)	NECESSARY	\$25.00	\$15.00
			\$25.00	\$15.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	RUSTPROOFING		\$100.00	\$30.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER		\$300.00	\$250.00
	SPRAY PAINTING		\$600.00	\$400.00
			\$1,000.00	\$680.00
GRAND TOTAL			\$2,375.00	\$1,497.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,200.00
Report Ref No: CS/MSG24060163/Kqh3e2				

KSC

KENNETH KONG SENG CHEONG