



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMH 3892B

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	DENTED/DEFORMED	\$683.60	\$683.60
2	REAR BUMPER PDC SENSOR - RH @\$212.60	SERVICEABLE	\$425.20	\$0.00
1	REAR BUMPER SIDE COVER - RH	GRAZED	\$68.80	\$68.80
1	REAR BUMPER DIFUSSER	CUT	\$190.30	\$190.30
1	REAR BUMPER REINFORCEMENT	DENTED/BENT	\$371.60	\$199.30
2	REAR BUMPER SIDE BRACKETS - R/L @\$45.50	NOT NECESSARY	\$91.00	\$0.00
2	REAR BUMPER SIDE RETAINERS - R/L @\$51.50	NOT NECESSARY	\$103.00	\$0.00
1	REAR BOOT LID	NOT NECESSARY	\$761.20	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$457.20	\$0.00
1	REAR TAILLAMP - RH	CRACKED	\$411.20	\$340.50
	<b>LESS 20.00% DISCOUNT</b>		(\$712.62)	(\$296.50)
			<b>\$2,850.48</b>	<b>\$1,186.00</b>
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIP (SN)	NECESSARY	\$50.00	\$30.00
			<b>\$50.00</b>	<b>\$30.00</b>
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK REAR WIRING		\$40.00	\$20.00
	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	NOT NECESSARY	\$100.00	\$0.00
	TO TUFF KOTE	NOT NECESSARY	\$60.00	\$0.00
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		\$800.00	\$500.00
	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL		\$800.00	\$400.00
			<b>\$1,800.00</b>	<b>\$920.00</b>
<b>GRAND TOTAL</b>			<b>\$4,700.48</b>	<b>\$2,136.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>\$1,700.00</b>
<b>Report Ref No: CS/INC24090279/Unh3</b>				



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

**TOTAL FOR SPARE PARTS: \$ 2,900.48 \$ 1,216.00**  
**TOTAL FOR LABOUR : \$ 1,800.00 \$ 920.00**  
**TOTAL REPAIR COST: \$ 4,700.48 \$ 2,136.00**

## **CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.