



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SBP 6331Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FRONT HEADLAMPS	O/S CRACKED / N/S NOT NECESSARY	\$3,960.00	\$1,280.00
2	FRONT HEADLAMP PANELS	TO REPAIR SEE LABOUR	\$231.00	\$0.00
2	FRONT HEADLAMP LOWER BRACKETS	NOT NECESSARY	\$283.40	\$0.00
2	FRONT BUMPER FOG LAMPS	NOT NECESSARY	\$962.80	\$0.00
2	FRONT BUMPER FOG LAMP COVERS	NOT NECESSARY	\$396.20	\$0.00
2	FRONT BUMPER SIDE RETAINERS	NOT NECESSARY	\$99.60	\$0.00
1	FRONT BUMPER NOZZLE COVER	NOT NECESSARY	\$80.60	\$0.00
2	FRONT FENDER INNER SHIELDS	NOT NECESSARY	\$220.60	\$0.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	\$625.50	\$0.00
1	FRONT BRACE PANEL	NOT NECESSARY	\$78.50	\$0.00
	LESS 10.00 / 20.00% DISCOUNT		(\$693.82)	(\$256.00)
			\$6,244.38	\$1,024.00
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BONNET-CARBON FIBRE (SN)	CRACKED	\$2,500.00	\$1,200.00
1	FRONT GRILLE ASSY (SN)	CRACKED	\$450.00	\$450.00
1	FRONT BUMPER-CARBON FIBRE (SN)	DENTED / TORN	\$2,000.00	\$800.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$80.00	\$30.00
1	FRONT NUMBER PLATE WITH HOLDER-CARBON FIBRE (SN)	DAMAGED	\$180.00	\$40.00
1	FRONT FENDER-RH (SN)	NOT NECESSARY	\$1,250.00	\$0.00
			\$6,460.00	\$2,520.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING		\$80.00	\$20.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT HEADLAMP PANELS AND FRONT SUPPORT PANEL		\$1,800.00	\$300.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS		\$1,600.00	\$550.00
			\$3,480.00	\$870.00
GRAND TOTAL			\$16,184.38	\$4,414.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$3,500.00
Report Ref No: CS/SMO24090283/Unp3			

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.