



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNN 3747U

| REPLACEMENT OF PARTS | | | | |
|----------------------|---|---------------|------------------------|-------------------|
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1 | FRONT BUMPER | TORN | \$1,387.50 | \$1,290.00 |
| 1 | FRONT BUMPER FOG LAMP LH | NOT NECESSARY | \$385.00 | \$0.00 |
| 1 | FRONT BUMPER FOG LAMP COVER LH | NOT NECESSARY | \$188.00 | \$0.00 |
| 1 | FRONT BUMPER FOG LAMP LOWER GARNISH LH | NOT NECESSARY | \$196.00 | \$0.00 |
| 1 | FRONT BUMPER SPONGE | NOT NECESSARY | \$198.20 | \$0.00 |
| 1 | HEADLAMP LH | NOT NECESSARY | \$2,864.30 | \$0.00 |
| 1 | FRONT FENDER INNER COWLING LH | NOT NECESSARY | \$233.97 | \$0.00 |
| 1 | FRONT ABS SENSOR LH | NOT NECESSARY | \$195.33 | \$0.00 |
| 1 | FRONT STEERING RACK AND PINION | NOT NECESSARY | \$4,380.89 | \$0.00 |
| 1 | FRONT KNUCKLE ARM LH | DAMAGED | \$870.99 | \$870.99 |
| 1 | FRONT KNUCKLE ARM BEARING LH | DAMAGED | \$531.60 | \$390.00 |
| 1 | FRONT LOWER ARM LH | BENT | \$560.70 | \$560.70 |
| 1 | FRONT STABILIZER BAR LINKAGE LH | NOT NECESSARY | \$138.70 | \$0.00 |
| 1 | FRONT SHOCK ABSORBER LH | NOT NECESSARY | \$764.80 | \$0.00 |
| | LESS 10.00% DISCOUNT | | (\$1,289.60) | (\$311.17) |
| | | | \$11,606.38 | \$2,800.52 |
| Special Nett | | | | |
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1 | FRONT WHEEL RIM LH (SN) | CUT | \$1,512.00 | \$800.00 |
| 1 | SET FRONT BUMPER CLIP (SN) | NECESSARY | \$80.00 | \$30.00 |
| 1 | SET FRONT BUMPER UNDER COVER CLIP (SN) | NOT NECESSARY | \$50.00 | \$0.00 |
| 1 | SET FRONT GRILLE (UPPER) CLIP (SN) | NOT NECESSARY | \$50.00 | \$0.00 |
| 1 | SET FRONT FENDER INNER COWLING CLIP RH (SN) | NOT NECESSARY | \$80.00 | \$0.00 |
| 1 | FRONT WHEEL TYRE RH (SN) | NOT NECESSARY | \$480.00 | \$0.00 |
| 1 | SET WHEEL CAP (SN) | NOT NECESSARY | \$100.00 | \$0.00 |
| 1 | BRAKE OIL (SN) | NOT NECESSARY | \$30.00 | \$0.00 |
| | | | \$2,382.00 | \$830.00 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

| Labour | | | | |
|--------------------------------------|---|---------------|------------------------|-------------------|
| | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| | PANEL BEATING, REMOVING AND REPLACING PARTS | | \$1,200.00 | \$200.00 |
| | SPRAY PAINTING TO AFFECTED AREA | | \$1,000.00 | \$200.00 |
| | TUFF COAT | NOT NECESSARY | \$250.00 | \$0.00 |
| | WIRING CHECK | | \$80.00 | \$30.00 |
| | REFOCUS HEADLAMP BEAM | NOT NECESSARY | \$80.00 | \$0.00 |
| | REMOVE AND REFIX FRONT UNDERCARRIAGE | | \$650.00 | \$200.00 |
| | FOUR WHEEL ALIGNMENT | | \$120.00 | \$80.00 |
| | REMOVE AND REFIX FRONT BUMPER SENSOR AND DISTANCE SETTING | NOT NECESSARY | \$180.00 | \$0.00 |
| | RESET ABS LIGHT | NOT NECESSARY | \$350.00 | \$0.00 |
| | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC | NOT NECESSARY | \$650.00 | \$0.00 |
| | | | \$4,560.00 | \$710.00 |
| GRAND TOTAL | | | \$18,548.38 | \$4,340.52 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | | \$3,450.00 |
| Report Ref No: CS/INC24090286/Aqh3e2 | | | | |

TOTAL FOR SPARE PARTS: \$ 13,988.38 \$ 3,630.52
TOTAL FOR LABOUR : \$ 4,560.00 \$ 710.00
TOTAL REPAIR COST: \$ 18,548.38 \$ 4,340.52

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repossibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.