



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24090286/Aqh3e2
75 BRAS BASAH ROAD	Date:	27/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDD 9918A	Veh. Inspected	SNN 3747U
Policy No.	-	Coverage	0
Claim No.	MT/1295536-001	Excess	\$0.00
Assign From	FIONA SHEN	Assign Date	17/09/2024

2. Vehicle Details

Make & Model	VOLKSWAGEN JETTA	C.C	1390
Engine No.	CAXF82926	Year of Reg.	11/11/2016
Chassis No.	WVWZZZ16ZGM010993	Colour	WHITE
Odometer	157786 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/40 R18	MICHELIN	6
L/H Front Tyre	225/40 R18	MICHELIN	6
R/H Rear Tyre	225/40 R18	MICHELIN	6
L/H Rear Tyre	225/40 R18	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/09/2024	Inspection Date	17/09/2024 (15:42)
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days