



**Lin's Brother Auto Engineering Workshop**  
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J liusbros@gmail.com

Tel: 67411730

### ESTIMATE

Name: MS First Capital Insurance Limited  
Address: Motor Claims Department  
16 Raffles Quay #42-01  
Hong Leong Building Singapore 048581

Ref Date: 13/09/2024  
Ref No: GBL1685E240911  
Vehicle No: GBL1685E  
Model / Make: Toyota Hiace  
Capacity: 2982 cc Van Turbo 5 DR MT

| Item # | Damaged Area   | Description                                                                     | Unit Price  | Qty | Estimation / Quotation | N / SN | Cost Of Repair |
|--------|----------------|---------------------------------------------------------------------------------|-------------|-----|------------------------|--------|----------------|
| 1      | Rear           | Tailgate <i>DD / Ref</i>                                                        | \$ 2,051.60 | 1   | \$ 2,051.60            |        | ✓              |
| 2      |                | Tailgate Lock <i>SN</i>                                                         | \$ 394.90   | 1   | \$ 394.90              |        | X              |
| 3      |                | Tailgate Weatherstrip <i>SN</i>                                                 | \$ 426.70   | 1   | \$ 426.70              |        | X              |
| 4      |                | Tailgate Outer Garnish <i>11</i>                                                | \$ 397.00   | 1   | \$ 397.00              |        | X              |
| 5      |                | Tailgate "Toyota" Motif <i>11</i>                                               | \$ 70.50    | 1   | \$ 70.50               |        | ✓              |
| 6      |                | Tailgate "70 KM/H" Sticker <i>11</i>                                            | \$ 15.00    | 1   | \$ 15.00               | SN     | 10 S/N         |
| 7      |                | Tailgate "8 PAX" Sticker <i>11</i>                                              | \$ 15.00    | 1   | \$ 15.00               | SN     | 10 S/N         |
| 8      |                | Bumper <i>DD</i>                                                                | \$ 599.50   | 1   | \$ 599.50              |        | ✓              |
| 9      |                | Bumper Clips 1 set <i>11</i>                                                    | \$ 65.00    | 1   | \$ 65.00               | SN     | 30 S/N         |
| 10     |                | Bumper Reverse Sensor <i>not function</i>                                       | \$ 220.00   | 1   | \$ 220.00              | SN     | 200 S/N        |
| 11     |                | End Panel Outer <i>50 S/N</i>                                                   | \$ 566.10   | 1   | \$ 566.10              |        | ✓              |
| 12     |                | End Panel Inner <i>11</i>                                                       | \$ 936.20   | 1   | \$ 936.20              |        | X              |
| 13     |                | End Panel Sealant <i>11</i>                                                     | \$ 50.00    | 1   | \$ 50.00               | SN     | 40 S/N         |
| 14     |                | Tailgate Windscreen Glass Moulding <i>NS</i>                                    | \$ 219.00   | 1   | \$ 219.00              |        | X              |
| 15     |                | Tailgate Windscreen Glass Sealant <i>11</i>                                     | \$ 50.00    | 1   | \$ 50.00               | SN     | 40 S/N         |
| 16     |                | "Corporate" Advertisement & Artwork <i>NT</i>                                   |             |     | \$ 300.00              | SN     | X              |
| 17     |                | Remove and refix rear tailgate components & wiper mechanism <i>repair</i>       |             |     | \$ 80.00               |        | 50             |
| 18     | <i>11/Head</i> | Remove and refix rear bumper reverse sensor                                     |             |     | \$ 100.00              |        | 30             |
| 19     |                | Remove & reinstall Tailgate Glass to facilitate repairs                         |             |     | \$ 120.00              |        | 100            |
| 20     |                | Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc            |             |     | \$ 800.00              |        | 680            |
| 21     |                | To putty & spray painting & including touch up paint on accident affected areas |             |     | \$ 700.00              |        | 500            |
| 22     |                | To apply Rust Proofing , reseal tuff-coating treatment on accident area         |             |     | \$ 80.00               |        | 50             |

Total Parts & Labour of estimate for damaged vehicle

\$ 8,256.50

Total amount in Lumpsum Basis for repaired vehicle

\$ 3,800.00

SDL Three Thousand Eight Hundred Only

Liu's Bro Auto Engrg Wks

*not Authorized*  
*11*  
*means*  
*16/9/24*  
*L/S \$ 3300*  
*take phd. Affly*  
*4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*P-3287-7*  
*252*  
*2465.78*  
*330*  
*1410*  
*4205.78*  
*202*  
*3364.*