

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBL 1685E

|     | REPLACEMENT OF PARTS                    |                      |                        |                   |
|-----|---|----------------------|------------------------|-------------------|
| Qty | Description of Parts                    | Condition            | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1   | REAR TAILGATE                           | DENTED/BENT          | \$2,051.60             | \$2,051.60        |
| 1   | REAR TAILGATE LOCK                      | SERVICEABLE          | \$394.90               | \$0.00            |
| 1   | REAR TAILGATE WEATHERSTRIP              | SERVICEABLE          | \$426.70               | \$0.00            |
| 1   | REAR TAILGATE OUTER GARNISH             | NOT NECESSARY        | \$397.00               | \$0.00            |
| 1   | REAR TAILGATE "TOYOTA" MOTIF            | NECESSARY            | \$70.50                | \$70.50           |
| 1   | REAR BUMPER                             | DENTED               | \$599.50               | \$599.50          |
| 1   | REAR END PANEL OUTER                    | BADLY DENTED         | \$566.10               | \$566.10          |
| 1   | REAR END PANEL INNER                    | TO REPAIR SEE LABOUR | \$936.20               | \$0.00            |
| 1   | REAR TAILGATE WINDSCREEN GLASS MOULDING | NO SUCH PARTS        | \$219.00               | \$0.00            |
|     | LESS 0.00 / 25.00% DISCOUNT             |                      | \$0.00                 | (\$821.93)        |
|     |   |                      | \$5,661.50             | \$2,465.77        |

|     | Special Nett                                  |             |                        |                   |
|-----|---|-------------|------------------------|-------------------|
| Qty | Description of Parts                          | Condition   | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1   | REAR TAILGATE "70 KM/H" STICKER (SN)          | NECESSARY   | \$15.00                | \$10.00           |
| 1   | REAR TAILGATE "8 PAX" STICKER (SN)            | NECESSARY   | \$15.00                | \$10.00           |
| 1   | SET REAR BUMPER CLIPS (SN)                    | NECESSARY   | \$65.00                | \$30.00           |
| 1   | REAR BUMPER REVERSE SENSOR (SN)               | MALFUNCTION | \$220.00               | \$200.00          |
| 1   | REAR END PANEL SEALANT (SN)                   | NECESSARY   | \$50.00                | \$40.00           |
| 1   | REAR TAILGATE WINDSCREEN GLASS SEALANT (SN)   | NECESSARY   | \$50.00                | \$40.00           |
| 1   | REAR "CORPORATE" ADVERTISEMENT & ARTWORK (SN) | NOT FITTED  | \$300.00               | \$0.00            |
|     |   |             | \$715.00               | \$330.00          |

| Labour  |           |                        |                   |
|---|-----------|------------------------|-------------------|
| Description of Parts  | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM   |           | \$80.00                | \$50.00           |
| REMOVE AND REPLACED REAR BUMPER REVERSE SENSOR  |           | \$100.00               | \$30.00           |
| REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS   |           | \$120.00               | \$100.00          |
| LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS. INCLUSIVE OF THE REPAIR OF END PANEL INNER |           | \$800.00               | \$680.00          |
| TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTECD AREAS                                  |           | \$700.00               | \$500.00          |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Labour   |                 |                        |                   |  |
|--|-----------------|------------------------|-------------------|--|
| Description of Parts   | Condition       | Workshop Estimate (\$) | Our Adjusted (\$) |  |
| TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA |                 | \$80.00                | \$50.00           |  |
|  |                 | \$1,880.00             | \$1,410.00        |  |
| GRAND TOTAL  |                 | \$8,256.50             | \$4,205.77        |  |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)   |                 |                        | \$3,300.00        |  |
| Report Ref No: CS/F  | Cl24090287/Uqp3 |                        |                   |  |

## **CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.