



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI24090287/Uqp3

Date: 26/09/2024

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6659T	Veh. Inspected	GBL 1685E
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008053MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	16/09/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE	C.C	2982
Engine No.	1KDB069797	Year of Reg.	24/03/2021
Chassis No.	JTFHT02P000251421	Colour	WHITE
Odometer	85973 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	AUSTONE	6
L/H Front Tyre	195R15	AUSTONE	6
R/H Rear Tyre	195R15	AUSTONE	6
L/H Rear Tyre	195R15	AUSTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/09/2024	Inspection Date	16/09/2024
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days