



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 7207D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT	BUCKLED	2,950.00	1,615.30
1	REAR BOOT LOGO	NECESSARY	196.00	196.00
1	REAR BOOT INNER LOCK	BENT	440.00	440.00
1	REAR BUMPER	DEFORMED	2,070.00	1,250.00
1	REAR BUMPER COVER	NOT NECESSARY	260.00	-
1	REAR BUMPER PARKING SENSOR LHS	CUT	295.00	295.00
1	REAR BUMPER PARKING SENSOR RHS	CUT	295.00	295.00
1	REAR BUMPER PARKING SENSOR RING LHS	NECESSARY	25.00	25.00
1	REAR BUMPER PARKING SENSOR RING RHS	NECESSARY	25.00	25.00
1	EXHAUST SILENCER	TO REPAIR SEE LABOUR	2,930.00	-
1	REAR BOOT SENSOR SUPPORT (ADDITIONAL)	CRACKED	120.00	120.00
1	REAR BUMPER BRACKET / GUIDE LHS (ADDITIONAL)	CRACKED	210.00	210.00
1	REAR BUMPER BRACKET / GUIDE RHS (ADDITIONAL)	CRACKED	210.00	210.00
	LESS 10% DISCOUNT		-1,002.60	-468.13
			9,023.40	4,213.17
	<u>SPECIAL NETT ITEMS</u>			
1	SEALANT (SN)	NECESSARY	35.00	35.00
			35.00	35.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE AND REINSTALL REAR WINDSCREEN. INCLUSIVE OF THE REPAIR OF EXHAUST SILENCER.		120.00	120.00
	CHECK WIRING FUNCTION.		40.00	40.00
	APPLY RUST PROOFING.		180.00	40.00
	REMOVE AND REFIT EXHAUST SILENCER.		180.00	80.00
	REMOVE NECESSARY PARTS. JACKING, PANEL BEATING, REPAIR AND STRAIGHTEN REAR INNER PANEL, REAR END PANEL INCLUSIVE REPLACING THE ABOVE.		900.00	500.00

Report Ref No. CS/SMO24090291/Dqp3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	PUTTY AND RESPRAY REAR INNER PANEL, REAR BOOT, REAR END PANEL AND REAR BUMPER.		900.00	500.00
			2,320.00	1,280.00
GRAND TOTAL			11,378.40	5,528.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,400.00

Report Ref No. CS/SMO24090291/Dqp3e2(N)

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.