



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLT 2216J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT HEADLAMP R/H	CUT	\$3,850.20	\$3,850.20
1	HEADLAMP BRACKET R/H	SERVICEABLE	\$95.30	\$0.00
1	FRONT BUMPER	CRACKED	\$725.30	\$725.30
1	FRONT BUMPER SIDE RETAINER R/H	SERVICEABLE	\$143.20	\$0.00
1	FRONT BUMPER TOW COVER R/H	DEFORMED	\$45.00	\$45.00
1	FRONT BUMPER LOWER GRILLE	CRACKED	\$1,369.20	\$1,369.20
1	FOG LAMP R/H	CRACKED	\$868.00	\$868.00
1	FOG LAMP GARNISH R/H	CRACKED	\$365.00	\$365.00
1	FRONT SUPPORT PANEL	SERVICEABLE	\$1,243.70	\$0.00
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	\$664.20	\$0.00
1	FRONT BUMPER SPONGE	CRACKED	\$139.60	\$139.60
1	FRONT BUMPER LOWER LIP	SERVICEABLE	\$342.60	\$0.00
1	FRONT BUMPER SPOILER	CRACKED	\$526.30	\$526.30
1	FRONT FENDER R/H	SERVICEABLE	\$875.00	\$0.00
1	FRONT FENDER INNER SHIELD	SERVICEABLE	\$399.20	\$0.00
1	FRONT GRILLE	SERVICEABLE	\$843.60	\$0.00
1	FRONT R/H SPONGE	CRACKED	\$79.80	\$79.80
1	FRONT BUMPER MOULDING	SCRATCHED	\$531.80	\$531.80
	<b>LESS 25.00% DISCOUNT</b>		(\$3,276.75)	(\$2,125.05)
			\$9,830.25	\$6,375.15

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
10	FRONT BUMPER CLIP @\$6.50 (SN)	NECESSARY	\$65.00	\$30.00
10	FRONT FENDER INNER SHIELD CLIP @\$6.50 (SN)	NOT NECESSARY	\$65.00	\$0.00
1	FRONT PARKING SENSOR (SN)	SCRATCHED	\$280.00	\$280.00
			\$410.00	\$310.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT DAMAGE PARTS TO FACILITATE REPAIR		\$1,200.00	\$500.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	SPRAY PAINT ALL AFFECTED AREA	NOT NECESSARY	\$1,000.00	\$250.00
	RUST PROOFING		\$90.00	\$0.00
	REPROGRAMME NEW MODULE TO ADAPTIVE HEADLAMP		\$240.00	\$150.00
			\$2,530.00	\$900.00
GRAND TOTAL			\$12,770.25	\$7,585.15
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$6,050.00
Report Ref No: CS/AGI24090293/Rqp3e2				

**MRB**

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.