

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090294/APA3Q2
Date: 07/02/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826_04
Claimant Vehicle No : SMA2314Y Insured Vehicle No : SND7698D
Date of Loss: 15/09/2024 Nature of Claim: TP Claim No: MFL2024D0010888

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMA2314Y
Make & Model: BMW 730LI, 2.0 LED NAV HUD SR (A) Engine No: 14185253B48B20B
Reg. Date: 31/05/2018 (Man. Year: 2018) Chassis No: WBA7E02060G913430
Colour: Black Odometer: 168693 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50 R18 Rear Tyre Size: 245/50 R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,039.25	10,300.00	3,739.25	26.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,340.00	630.00	710.00	52.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,379.25	10,930.00	4,449.25	28.93
Approved Total (Overridden) (S\$)		8,700.00		
(S\$)	15,379.25	8,700.00	6,679.25	43.43
+ GST 9.00/9.00% (S\$)	1,384.13	783.00	601.13	43.43
Nett Amount (S\$)	16,763.38	9,483.00	7,280.38	43.43
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		10,010.25		
Global Sum Settlement (S\$)		10,000.00		

INSPECTION

Date of Assignment: 17/09/2024
Date Inspected: 17/09/2024 Inspected At: N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Dec 2024)
Parts:	143	BMW 730LI 2.0 LED NAV HUD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA2314Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,250.00 FL	*2,250.00 FL
2	1		*FRONT BUMPER LH FOGLAMP	Not Necessary	410.00 FL	*- FL
3	1		*FRONT BUMPER LH FOGLAMP GARNISH	Not Necessary	295.00 FL	*- FL
4	1		*FRONT BUMPER LH FOGLAMP GARNISH OUTER CHROME MOULDING	Cracked	230.00 FL	*230.00 FL
5	1		*FRONT BUMPER LH INNER BRACKET	Cracked	155.00 FL	*155.00 FL
6	1		*FRONT BUMPER LH LOWER CHROME MOULDING	Cracked	275.00 FL	*275.00 FL
7	1		*FRONT BUMPER LH SIDE RETAINER	Not Necessary	165.00 FL	*- FL
8	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	110.00 FL	*- FL
9	1		*FRONT BUMPER NUMBER PLATE GARNISH	Deformed	105.00 FL	*105.00 FL
10	4		*FRONT BUMPER PARKING SENSOR	Not Necessary	840.00 FL	*- FL
11	4		*FRONT BUMPER PARKING SENSOR O RING	Not Necessary	100.00 FL	*- FL
12	4		*FRONT BUMPER PARKING SENSOR HOLDER	Not Necessary	140.00 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	895.00 FL	*- FL
14	1		*FRONT BUMPER SPONGE	Not Necessary	540.00 FL	*- FL
15	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	55.00 FL	*- FL
16	1		*FRONT GRILLE	Cracked	1,450.00 FL	*1,450.00 FL
17	1		*FRONT GRILLE OUTER CHROME MOULDING L/R	N/S Cracked	730.00 FL	*365.00 FL
18	1		*FRONT LH HEADLAMP	Cracked	5,870.00 FL	*5,870.00 FL
19	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
20	1		*FRONT BUMPER NUMBER PLATE	Deformed	25.00 FS	*25.00 FS
21	1		*FRONT BUMPER NUMBER PLATE FRAME	Deformed	50.00 FS	*30.00 FS
22	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,770.00	10,835.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	730.75	535.00
Total Parts (\$\$)	14,039.25	10,300.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING (TO FR)	New	80.00	80.00
2	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	600.00	250.00
3	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	600.00	300.00
4	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	60.00	0.00
Gross Labour Cost (\$\$)			1,340.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >