

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III24060166/KQH3M4**Date:** 09/07/2024**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D23MFL0002571
Claimant Vehicle No :	GBE3395R	Insured Vehicle No :	SLR4617H
Date of Loss:	13/06/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE3395R	Engine No:	1KD2462568
Make & Model:	TOYOTA HIACE, 3.0 D DX (M)	Chassis No:	KDH2010154203
Reg. Date:	11/11/2015 (Man. Year: 2014)	Odometer:	210910 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Falken 4 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Falken 4 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,227.11	3,752.37	6,474.74	63.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,250.00	1,750.00	58.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,227.11	5,002.37	8,224.74	62.18
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	13,227.11	4,000.00	9,227.11	69.76

INSPECTION

Date of Assignment:	20/06/2024	
Date Inspected:	21/06/2024	Inspected At: BLK 5034 ANG MO KIO INDUSTRIAL PARK 2 #01-341 SINGAPORE 569537 REPAIRER: JD MOTORSPORTS PTE LTD
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jul 2024)
Parts:	213	TOYOTA HIACE 3.0 D DX (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE3395R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,685.40 F	*1,685.40 FL
2	1		*TAILGATE INNER LOCK	Jammed	328.70 F	*328.70 FL
3	1		*TAILGATE INNER LOCK COVER	Serviceable	85.60 F	*- FL
4	1		*TAILGATE CATCH LOCK	Distorted	130.20 F	*130.20 FL
5	1		*TAILGATE INNER TRIM BOARD	Serviceable	258.60 F	*- FL
6	1		*TAILGATE WEATHERSTRIP	Serviceable	256.01 F	*- FL
7	2		*TAILGATE DAMPER	Serviceable	603.40 F	*- FL
8	1		*TAILGATE OUTER HANDLE	Serviceable	120.80 F	*- FL
9	2		*SET TAILGATE STOPPER	Serviceable	320.60 F	*- FL
10	1		*TAILGATE OUTER GARNISH	Serviceable	430.20 F	*- FL
11	1		*TAILGATE KEY SWITCH	Serviceable	156.70 F	*- FL
12	1		*TAILGATE EMBLEM LOGO	Necessary	180.30 F	*75.30 FL
13	1		*TAIL LAMP	N/S Cut	760.60 F	*380.30 FL
14	1		*REAR BUMPER	Bent/Cracked	673.50 F	*673.50 FL
15	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	197.80 F	*98.90 FL
16	2		*REAR CORNER PANEL	Serviceable	330.40 F	*- FL
17	2		*REAR TOWING COVER	No such part	130.60 F	*- FL
18	1		*REAR END PANEL	Bent	896.40 F	*708.10 FL
19	1		*REAR INNER STEP GARNISH	Serviceable	319.80 F	*- FL
20	1		*REAR FLOOR PANEL (NPA)	Repair	0.00 F	*- FL
21	1		*REAR FLOOR CARPET	Serviceable	649.50 F	*- FL
22	1		*REAR UNDER SPARE TYRES BRACKET	Bent	656.40 F	*388.10 FL
23	1		*REAR UNDER SPARE TYRES BRACKET HOOK	Repair	147.60 F	*- FL
24	12		*TAILGATE TRIM BOARD CLIP	Not Necessary	72.00 FS	*- FS
25	6		*REAR BUMPER CLIP	Necessary	36.00 FS	*36.00 FS
26	2		*PARKING SENSOR	Cut	560.00 FS	*200.00 FS
27	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
28	1		*HIACE STICKER	Necessary	60.00 FS	*60.00 FS
29	1		*70KM STICKER	Necessary	30.00 FS	*15.00 FS
30	1		*1250KG STICKER	Necessary	30.00 FS	*30.00 FS
31	2		*BUMPER REFLECTOR STICKER	Necessary	60.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,227.11	4,869.50
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,117.13
Total Parts (S\$)	10,227.11	3,752.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	New	1,800.00	600.00
2	TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	New	600.00	450.00
3	TO SUPPLY LABOUR FOR REMOVE AND REFIT REAR WINDSCREEN	New	250.00	120.00
4	TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	New	250.00	60.00
5	TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	New	100.00	20.00
Gross Labour Cost (\$\$)			3,000.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >