

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24090300/TPA3Q2**Date:** 14/01/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826_03
Claimant Vehicle No : FBS8292Y **Insured Vehicle No :** SNH4442Z
Date of Loss: 26/08/2024 Nature of Claim: TP Claim No: MFL2024D0010090

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBS8292Y**
Make & Model: YAMAHA T150, 150cc Engine No: G3P3E0002056
Reg. Date: 17/08/2021 (Man. Year: 2020) Chassis No: MH3UG131000002072
Colour: Black/Grey Odometer: 0 km
Engine Capacity: 150 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80 R17 Rear Tyre Size: 120/70 R17
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,274.10	6,451.50	2,822.60	30.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	880.00	250.00	22.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,404.10	7,331.50	3,072.60	29.53
Approved Total (Overridden) (S\$)		5,850.00		
(S\$)	10,404.10	5,850.00	4,554.10	43.77
+ GST 9.00/9.00% (S\$)	936.37	526.50	409.87	43.77
Nett Amount (S\$)	11,340.47	6,376.50	4,963.97	43.77
+ Loss of Use (5.0 x S\$25.00/day) (S\$)		125.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		6,503.68		
Global Sum Settlement (S\$)		6,500.00		

INSPECTION

Date of Assignment: 18/09/2024
Date Inspected: 18/09/2024 Inspected At: Yew Tee Automobile Tech Pte Ltd (Woodlands)
39 Woodlands Close #01-12, Mega@Woodlands
Singapore 737856
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 Dec 2024)	
Parts:	N/A	YAMAHA T150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBS8292Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FRONT FORK	Bent	669.00 FL	*500.00 FL
2	1		*FRONT FENDER	Cracked	170.00 FL	*120.00 FL
3	1		*FRONT FENDER INNER SHIELD	Distorted	220.00 FL	*120.00 FL
4	1		*FRONT FAIRING	Distorted	350.00 FL	*250.00 FL
5	1		*FRONT FAIRING CENTRE	Distorted	280.00 FL	*180.00 FL
6	1		*FRONT FAIRING LAMP	Cracked	480.00 FL	*380.00 FL
7	1		*FRONT FAIRING INNER FAIRING	Deformed	380.00 FL	*280.00 FL
8	1		*FRONT HEADLAMP	Cut	470.00 FL	*370.00 FL
9	1		*FRONT HEADLAMP FAIRING	Cut	310.00 FL	*210.00 FL
10	1		*FRONT HEADLAMP LOWER FAIRING	Missing	330.00 FL	*230.00 FL
11	1		*FRONT SIDE MIRROR LH	Cut	85.00 FL	*85.00 FL
12	1		*FRONT SIDE MIRROR RH	Broken	85.00 FL	*85.00 FL
13	1		*FRONT HANDLE BAR	Not Necessary	270.00 FL	*- FL
14	1		*FRONT HANDLE BAR GRIP RH	Cut	65.00 FL	*65.00 FL
15	1		*FRONT BRAKE LEVER RH	Cut	45.00 FL	*45.00 FL
16	1		*FRONT CLUTCH LEVER LH	Cut	45.00 FL	*45.00 FL
17	1		*FRONT STEERING CONE	Bent	165.00 FL	*120.00 FL
18	1		*CHASSIS FRAME (NPA)	Repair	0.00 FL	*- FL
19	1		*ENGINE COVER RH	Cracked	420.00 FL	*320.00 FL
20	1		*FRONT SIDE FAIRING LH	Distorted	360.00 FL	*260.00 FL
21	1		*FRONT SIDE FAIRING RH	Missing	360.00 FL	*260.00 FL
22	1		*RADIATOR	Bent	600.00 FL	*450.00 FL
23	1		*CENTRE FAIRING LH	Deformed	280.00 FL	*180.00 FL
24	1		*CENTRE FAIRING RH	Deformed	280.00 FL	*180.00 FL
25	1		*REAR FAIRING RH	Cut	330.00 FL	*230.00 FL
26	1		*FRONT FOOT BRAKE RH	Bent	220.00 FL	*120.00 FL
27	1		*FRONT FOOT REST RH	Dented	45.00 FL	*45.00 FL
28	1		*FRONT FOOT REST BRACKET RH	Bent	165.00 FL	*110.00 FL
29	1		*REAR EXHAUST PIPE	Bent	1,180.00 FL	*800.00 FL
30	1		*REAR EXHAUST PIPE OUTER COVER RH	Cut	210.00 FL	*110.00 FL
31	1		*REAR EXHAUST PIPE OUTER TAILCOVER RH	Cut	170.00 FL	*90.00 FL
32	1		*REAR FOOT REST RH	Broken	45.00 FL	*45.00 FL
33	1		*REAR FOOT REST BRACKET RH	Repair	165.00 FL	*- FL
34	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*20.00 FS
35	1		*FRONT WHEEL RIM	Bent	250.00 FS	*200.00 FS
36	1		*FRONT TYRE (80%)	Punctured	250.00 FS	*200.00 FS
37	1		*ENGINE COVER GASKET RH	Necessary	70.00 FS	*70.00 FS
38	1		*ENGINE OIL	Necessary	120.00 FS	*80.00 FS
39	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS
40	1		*ERP UNIT	Distorted	190.00 FS	*190.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,199.00	7,080.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	924.90	628.50
Total Parts (\$\$)	9,274.10	6,451.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO ELECTRICAL WIRING SERVICES	New	40.00	30.00
2	TO DISMANTLE & REFIT FRONT UNDERCARRIAGE	New	150.00	120.00
3	TO COMPUTER WHEEL BALANCING	New	60.00	30.00
4	TO REMOVE ,REFIX REALIGN ADJUST AND REPLACE ALL DAMAGED PARTS	New	480.00	450.00
5	TO UNDERCOATING FOR RUST PROTECTION	New	50.00	0.00
6	TO RESPRAY PAINT OF ACCIDENT SECTION	New	350.00	250.00
Gross Labour Cost (\$\$)			1,130.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >