

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090301/AUA3Q2**Date:** 17/06/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700003250
Claimant Vehicle No :	GBF7457P	Insured Vehicle No :	SLN4869T
Date of Loss:	10/09/2024	Nature of Claim:	TP
		Claim No:	4458768639SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF7457P	Engine No:	1KD2652487
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	KDH2010206674
Reg. Date:	07/03/2017 (Man. Year: 2016)	Odometer:	197421 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,587.32	5,429.95	9,157.37	62.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,200.00	1,950.00	4,250.00	68.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,787.32	7,379.95	13,407.37	64.50
Approved Total (Overridden) (S\$)		5,900.00		
Nett Amount (S\$)	20,787.32	5,900.00	14,887.32	71.62
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,727.25		
Global Sum Settlement (S\$)		6,700.00		

INSPECTION

Date of Assignment:	11/09/2024	
Date Inspected:	11/09/2024	Inspected At: Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,426.80 FL	*2,350.00 FL
2	1		*TAILGATE BADGE	Necessary	95.20 FL	*95.20 FL
3	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	78.20 FL	*78.20 FL
4	1		*TAILGATE WINDSCREEN MOULDING	Necessary	134.80 FL	*134.80 FL
5	1		*TAILGATE OUTER GARNISH	Not Necessary	398.60 FL	*- FL
6	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FL	*- FL
7	2		*TAILGATE NUMBER PLATE LAMPS	Not Necessary	179.20 FL	*- FL
8	1		*TAILGATE INNER LOCK	Damaged	461.60 FL	*385.00 FL
9	1		*TAILGATE INNER LOCK COVER	Cracked	125.80 FL	*45.00 FL
10	1		*TAILGATE INNERTRIM	Torn	428.90 FL	*165.00 FL
11	1		*SET TAILGATE INNERTRIM CLIPS	Necessary	30.00 FL	*30.00 FL
12	1		*TAILGATE LOCK CATCH	Not Necessary	56.00 FL	*- FL
13	1		*TAILGATE WEATHERSTRIP	Cut	411.90 FL	*375.00 FL
14	2		*TAILGATE SIDE STOPPER (MALE)	Not Necessary	72.00 FL	*- FL
15	2		*TAILGATE SIDE STOPPER (FEMALE)	Not Necessary	78.00 FL	*- FL
16	2		*TAILGATE HINGES	Not Necessary	171.80 FL	*- FL
17	2		*TAILGATE ABSORBER	Not Necessary	531.60 FL	*- FL
18	1		*TAIL WINDSCREEN MOULDING	Repeated	215.40 FL	*- FL
19	1		*TAIL WINDSCREEN INNER SEAL	Repeated	95.00 FL	*- FL
20	2		*TAILLAMPS	Cracked	871.60 FL	*790.00 FL
21	2		*TAILLAMPS INNER SEALER	Not Necessary	100.00 FL	*- FL
22	2		*SET TAILLAMPS CLIPS	Not Necessary	50.00 FL	*- FL
23	2		*TAILLAMPS PANELS	Repair	1,083.40 FL	*- FL
24	1		*REAR BUMPER WITH STEP	Deformed	778.80 FL	*778.80 FL
25	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	209.20 FL	*- FL
26	4		*REAR BUMPER STAY	Not Necessary	166.40 FL	*- FL
27	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
28	1		*SET REAR BUMPER WIRING HARNESS	Not Necessary	1,359.60 FL	*- FL
29	2		*REAR CORNER BUMPER	Not Necessary	551.20 FL	*- FL
30	2		*REAR CORNER BUMPER RETAINER	Not Necessary	224.00 FL	*- FL
31	2		*SET REAR CORNER BUMPER CLIPS	Not Necessary	40.00 FL	*- FL
32	1		*END PANEL (INNER)	Repair	1,165.80 FL	*- FL
33	1		*SET END PANEL (INNER)CLIPS	Not Necessary	40.00 FL	*- FL
34	1		*END PANEL (OUTER)	Dented	789.60 FL	*789.60 FL
35	1		*SETS END PANEL OUTER CLIPS	Not Necessary	40.00 FL	*- FL
36	1		*END PANEL TOP PLATE	Not Necessary	326.80 FL	*- FL
37	1		*REAR FLOOR PANEL (REAR PORTION)	Repair	1,848.50 FL	*- FL
38	1		*SPARE TYRE CARRIER	Not Necessary	359.70 FL	*- FL
39	1		*SPARE TYRE CARRIER BOLT	Not Necessary	58.20 FL	*- FL
40	1		*SPARE TYRE CARRIER NUT	Not Necessary	69.50 FL	*- FL
41	1		*TAILGATE STICKER 70KM/H	Necessary	25.00 FS	*15.00 FS
42	1		*TAILGATE STICKER TOYOTA	Necessary	65.00 FS	*30.00 FS
43	1		*TAILGATE STICKER HIACE	Necessary	65.00 FS	*30.00 FS
44	1		*COMPANY STICKER CUSTOMIZE	Necessary	800.00 FS	*500.00 FS
45	1		*REAR FLOOR BOARD	Not Necessary	600.00 FS	*- FS
46	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
47	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*60.00 FS
48	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
49	1		*SET REVERSE SENSOR CAMERA	Not Necessary	350.00 FS	*- FS
50	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,638.10	6,941.60
- List Item Discount on L Items 25.00/25.00% (\$)	4,050.78	1,511.65
Total Parts (\$)	14,587.32	5,429.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,200.00	800.00
2	SPRAY PAINTING	New	1,800.00	600.00
3	ANTI RUST	New	180.00	80.00
4	REMOVE AND INSTALL REAR WINDSCREEN	New	120.00	120.00
5	REMOVE AND INSTALL WOODEN BOARD	New	160.00	0.00
6	REMOVE AND INSTALL TAILGATE PARTS	New	120.00	80.00
7	REMOVE AND INTERIOR UPHOLSTERY	New	150.00	80.00
8	REMOVE AND INSTALL REVERSE SENSOR	New	120.00	50.00
9	REMOVE AND INSTALL REVERSE CAMERA	New	150.00	50.00
10	REPAIR AND REALIGN CHASSIS MEMBER	New	350.00	0.00
11	TO RESET ECU SYSTEM AND CALIBRATION	New	350.00	0.00
12	TO APPLY UNDERCOAT AND SEALANT TO AFFECTED AREA	New	380.00	60.00
13	CHECK WIRING ON TAILLAMPS	New	120.00	30.00
Gross Labour Cost (\$\$)			6,200.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >