

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090302/AUA3Q2**Date:** 10/04/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7240062117
Claimant Vehicle No : SLD6237G **Insured Vehicle No :** SNQ6840Y
 Date of Loss: 06/09/2024 Nature of Claim: TP Claim No: 3486966508SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD6237G**
 Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: 10JBHC3015361
 Reg. Date: 24/06/2016 (Man. Year: 2015) Chassis No: VF38DBHZTFL037400
 Colour: Grey Odometer: 232899 km
 Engine Capacity: 1560 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Royal Black 6 mm Rear Left Side: Royal Black 6 mm
 Front Right Side: Royal Black 6 mm Rear Right Side: Royal Black 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,534.00	5,081.80	6,452.20	55.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,850.00	1,350.00	3,500.00	72.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,384.00	6,431.80	9,952.20	60.74
Approved Total (Overridden) (S\$)		5,150.00		
(S\$)	16,384.00	5,150.00	11,234.00	68.57
+ GST 9.00/9.00% (S\$)	1,474.56	463.50	1,011.06	68.57
Nett Amount (S\$)	17,858.56	5,613.50	12,245.06	68.57
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		5,940.75		

INSPECTION

Date of Assignment: 12/09/2024
 Date Inspected: 12/09/2024 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,347.00 FL	*- FL
2	1		*BOOTLID LOWER GARNISH	Cracked	587.00 FL	*587.00 FL
3	1		*BOOTLID LOGO	Necessary	132.00 FL	*132.00 FL
4	1		*BOOTLID EMBLEM PEUGEOT	Necessary	98.00 FL	*98.00 FL
5	1		*BOOTLID EMBLEM 508	Necessary	88.00 FL	*88.00 FL
6	1		*BOOT LID TOP LOCK	Not Necessary	111.00 FL	*- FL
7	1		*BOOT LID LOWER LOCK	Not Necessary	111.00 FL	*- FL
8	1		*BOOT LID DETECTOR	Not Necessary	352.00 FL	*- FL
9	2		*BOOT LID HINGE	Not Necessary	272.00 FL	*- FL
10	1		*BOOT LID WEATHERSTRIP	Cut	277.00 FL	*277.00 FL
11	1		*REAR BUMPER	Deformed	1,065.00 FL	*1,065.00 FL
12	1		*REAR BUMPER LOWER (CENTER)	Deformed	252.00 FL	*252.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	477.00 FL	*477.00 FL
14	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	130.00 FL	*- FL
15	2		*REAR BUMPER SIDE REFLECTOR CHROME	Not Necessary	170.00 FL	*- FL
16	2		*REAR BUMPER NUMBER PLATE LAMP	Not Necessary	190.00 FL	*- FL
17	1		*REAR BUMPER TOWING COVER	Not Necessary	76.00 FL	*- FL
18	1		*REAR BUMPER ABSORB GARNISH	Deformed	228.00 FL	*228.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Not Necessary	230.00 FL	*- FL
20	2		*TAIL LAMP	Cracked	1,730.00 FL	*1,730.00 FL
21	2		*TAIL LAMP LOWER BRACKET	Not Necessary	192.00 FL	*- FL
22	1		*REVERSE CAMERA	Not Necessary	1,358.00 FL	*- FL
23	2		*REVERSE SENSOR	Damaged	984.00 FL	*500.00 FL
24	6		*REVERSE SENSOR HOLDER	Not Necessary	372.00 FL	*- FL
25	2		*REAR FENDER INNER COWLING	Not Necessary	392.00 FL	*- FL
26	1		*REAR END PANEL	Repair	971.00 FL	*- FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	168.00 FL	*168.00 FL
28	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
30	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
31	1		*SET REAR FENDER INNER COWLING	Not Necessary	50.00 FS	*- FS
32	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
34	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$) **12,770.00** **5,642.00**
- List Item Discount on L Items 10.00/10.00% (\$) 1,236.00 560.20

Total Parts (\$) **11,534.00** **5,081.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	600.00
3	TUFF COAT	New	250.00	30.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	250.00	40.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	0.00
8	TRANFER BOOT LID MECHANISM	New	80.00	0.00
9	CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	380.00	0.00
Gross Labour Cost (\$\$)			4,850.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >