

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090303/APA3Q2**Date:** 17/01/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220052035
Claimant Vehicle No :	SNP7872D	Insured Vehicle No :	SLH2999X
Date of Loss:	12/09/2024	Nature of Claim:	TP
		Claim No:	6262135486SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNP7872D		
Make & Model:	HONDA JAZZ, 1.4 (A)	Engine No:	L13A54003029
Reg. Date:	15/09/2007 (Man. Year: 2007)	Chassis No:	JHMGD18507S228573
Colour:	Red	Odometer:	165482 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,565.60	3,151.76	6,413.84	67.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,890.00	1,470.00	2,420.00	62.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,455.60	4,621.76	8,833.84	65.65
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	13,455.60	3,700.00	9,755.60	72.50
+ GST 9.00/9.00% (S\$)	1,211.00	333.00	878.00	72.50
Nett Amount (S\$)	14,666.60	4,033.00	10,633.60	72.50
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		4,535.18		

INSPECTION

Date of Assignment:	12/09/2024	
Date Inspected:	12/09/2024	Inspected At: Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	508.60 FL	*508.60 FL
2	1		*FRONT BUMPER LOWER COVER	Not Necessary	198.50 FL	*- FL
3	1		*FRONT BUMPER TOWING COVER	Not Necessary	35.80 FL	*- FL
4	1		*FRONT BUMPER SIDE VENT LH	Not Necessary	52.30 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	385.60 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	68.20 FL	*- FL
7	1		*HEADLAMP LH	Cut	685.90 FL	*685.90 FL
8	1		*HEADLAMP LOWER BRACKET	Not Necessary	65.80 FL	*- FL
9	1		*FRONT FENDER LH	Distorted	423.60 FL	*423.60 FL
10	1		*FRONT FENDER INNER COWLING LH	Deformed	135.80 FL	*135.80 FL
11	1		*FRONT WHEEL HOUSE PANEL LH	Repair	523.60 FL	*- FL
12	2		*FRONT DOOR HINGE	Not Necessary	138.40 FL	*- FL
13	1		*FRONT DOOR CHECKER	Not Necessary	65.30 FL	*- FL
14	1		*FRONT DOOR LH	Repair	1,043.20 FL	*- FL
15	1		*SIDE MIRROR ASSY LH	Not Necessary	698.70 FL	*- FL
16	1		*FRONT RIM LH	Cut	766.56 FS	*500.00 FS
17	1		*FRONT SHOCK ABSORBER LH	Bent	398.50 FL	*398.50 FL
18	1		*FRONT KNUCKLE ARM LH	Damaged	402.30 FL	*402.30 FL
19	1		*FRONT WHEEL HUB BEARING LH	Damaged	345.60 FL	*345.60 FL
20	1		*FRONT LOWER ARM	Bent	339.40 FL	*339.40 FL
21	1		*FRONT TIE ROD END	Not Necessary	59.80 FL	*- FL
22	1		*STEERING RACK AND PINION	Not Necessary	2,431.40 FL	*- FL
23	1		*FRONT DRIVESHAFT	Not Necessary	983.60 FL	*- FL
24	1		*SIDESKIRT LH	Not Necessary	458.90 FL	*- FL
25	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
26	1		*FRONT TYRE	Not Necessary	280.00 FS	*- FS
27	1		*SET FENDER INNER COWLING CLIPS	Necessary	30.00 FS	*30.00 FS
28	1		*POWER STEERING OIL	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,655.36	3,799.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,089.76	647.94
Total Parts (\$\$)	9,565.60	3,151.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD ,CUT ,KNOCK GRAZE ADJUST	New	1,200.00	500.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX	New	1,200.00	600.00
3	TO SPRAY TOUGH COAT ,RUST PROOFING	New	250.00	60.00
4	WIRING BULB CHECKING	New	120.00	30.00
5	REMOVE AND REFIX FRONT UNDER CARRIAGE	New	550.00	200.00
6	TRANSFER FRONT DOOR MECHANISM	New	80.00	0.00
7	COMPUTERISED WHEEL ALIGNMENT (BEFORE AND AFTER)	New	120.00	80.00
8	TOWING CHARGES (KING ROLLER)	New	120.00	0.00
9	TO SET ,CALIBRATE ABS SENSOR ELECTRONIC POWER STEERING SYSTEM	New	250.00	0.00
Gross Labour Cost (\$\$)			3,890.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >