



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNL 8109P

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	TORN	\$917.40	\$917.40
1	REAR BUMPER LOWER DIFFUSER	CUT	\$333.40	\$333.40
2	REAR BUMPER REVERSE SENSOR @\$294.20	NOT NECESSARY	\$588.40	\$0.00
4	REAR BUMPER REVERSE SENSOR 'O' RING @\$25.00	NOT NECESSARY	\$100.00	\$0.00
4	REAR BUMPER REVERSE SENSOR HOLDER @\$65.60	NOT NECESSARY	\$262.40	\$0.00
1	REAR BUMPER RH REFLECTOR	NOT NECESSARY	\$249.20	\$0.00
1	REAR BUMPER RH SIDE RETAINER	NOT NECESSARY	\$25.50	\$0.00
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	\$21.60	\$0.00
1	REAR RH KNUCKLE ARM	NOT NECESSARY	\$342.60	\$0.00
1	REAR RH KNUCKLE ARM BEARING	NOT NECESSARY	\$266.60	\$0.00
	<b>LESS 10.00 / 20.00% DISCOUNT</b>		(\$310.71)	(\$250.16)
			<b>\$2,796.39</b>	<b>\$1,000.64</b>
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR RH SPORT RIM (SN)	CUT	\$808.74	\$450.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$30.00
1	REAR RH TYRE (SN)	NOT NECESSARY	\$380.00	\$0.00
			<b>\$1,238.74</b>	<b>\$480.00</b>
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR		\$80.00	\$80.00
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION	NOT NECESSARY	\$120.00	\$0.00
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM		\$100.00	\$80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$500.00	\$200.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT		\$500.00	\$200.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	NOT NECESSARY	\$60.00	\$0.00
			\$1,360.00	\$560.00
GRAND TOTAL			\$5,395.13	\$2,040.64
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,600.00
Report Ref No: CS/FCI24090307/Avp3m4				

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.